CORNER RECORD	Document N	umber A.P.N	. 164-071-007
City ofMarinwood		Marin	, California
Brief Legal Description Lot 661 9 RM 32	,		
CORNER TYP	PE		COORDINATES (Optional)
Government Comer	Control Bronouty R	N	
	Property 🔀 Other 🗌		Datum
Rancho Date of Survey 10/5/99		Elev.	
Corner — Left as found [] Found and tagged [Established	☐ Reestablis	hed 🛭 Rebuilt 🗌
dentification and type of corner found: Evidence used to ic Found steel pins in monument wells	lentify or procedur on the cen	e used to establis terline of	h or reestablish the comer: Blackberry Lane
as shown on 9 RM 32.			
	· · · · · · · · · · · · · · · · · · ·		

A description of the physical condition of the monument a and tag RCE 18221 at the Southwest	s found and as se corner of	torreset: <u>Set</u> Lot 661 as	3/4" iron pipe shown on 9 RM 32
Also set crosscut in sidewalk on So			
line.			
			PROFESSIONAL
			SPROFESSIONAL SOLUTION OF THE PROFESSION OF THE
SURVEYOR'S STATEMENT			18/8
This Corner Record was prepared by me or under my d	irection in confor	mance with	(F) No. 18221
he Land Surveyors' Act on DEC EMBER 14			Exp. 6-30-01
ne Land Surveyors Act on	_ 19 ;	>- 4	The court is
igned R.C.E. N	Number	221_	OF CALLFOR
COUNTY SURVEYOR'S STATEM	EN:T		PROFESSIONAL
			M. WOO
his Corner Record was received	19 74 and	dexamined	
and filed DECEMBERP1, 1999.			No.26450
igned John M. Wooling T	itle _ DEPU	TY	Eq. 331-20 A
			OF CALLED
County Surveyor's Comment			Visi
, 5-1-5,0 5 50			

