


CORNER RECORD

Document Number 169.181.06

City of SAN Geronimo

County of MARIN, California

Brief Legal Description PARCEL 1, 16 PM 33



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 4/12/2001

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Reset the MOST SOUTHWESTERLY CORNER TO PARCEL 1
OF 16 PM 33 (FORMERLY A MARIN CO. HUB & TAG).
SET FROM EXISTING STANDARD STREET MAP SHOWN
ON 16 PM 33. SEE SKETCH ON REVERSE SIDE


A description of the physical condition of the monument as found and as set or reset:

SET NAIL IN ASPHALT PAVEMENT OF TAMARACK ROAD

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 18 2001

Signed [Signature] P.L.S or R.C.E. No. PLS 5379
Renewal 6.30.04



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 11, 2001

and examined and filed MAY 15, 2001

Signed [Signature] P.L.S or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment _____

BY 845 Olive St. Novato, CA
D) SCRANTON SURVEYING
Prepared

NOTE:

ALL DISTANCES GIVEN
IN FEET & DECIMALS THEREOF
NO EASEMENTS ARE DEPICTED

SCALE 1" = 10 FT.



PARCEL ONE
16 PM 33

MON. NO. 2 of 10 05 73
STONE MARKER WITH
CHISELED "X"

WIDENING STRIP
535 OR 34

N 21° 00' 54" W
378.30'

"BASIS see
S 83° 27' 11" E

N 85° 21' E

16 PM 33
BEARING "

73.38'
N 46° 41' E

TAMARACK
ROAD

N 85° 21' E
(10 05 73)
center line

15'

"THIS
CORNER
RECORD"

TIE:
S 81° 33' 46" W
597.04'

N 46° 41' E

STANDARD
STREET
MONUMENT

● = set NAIL IN PAVEMENT

SEE 16 PM 33 OR 10 05 73 FOR ADDITIONAL
DETAIL; NAIL SET FORMERLY MARIN CO. HUB & TAG