City of <u>San Ro</u>		County of M	arin	, California
Diloi Logai Doso	iption <u>Perpetuate & Re—Establish t</u> of Catalina Blvd. & Hyannis			•
1	CORNER TYPE Government Corner Co	E. N ntrol □ E operty □ Zon NAC her ☑ Elev Veri	eN/083Epoch Datum: NGVD29 is. Units: Metric	S (Optional) AD27 NAD83
Corner -	Left as found ☐ Found and tagged ☐	Established	Reestablished [2	〗 Rebuilt □
The City Str to perpetuat No attempt	ype of corner found: Evidence used to identify of eet Monument in the intersection of e its position prior to sewer line of was made to determine the validities in the area.	of Catalina Blvd construction an	d. & Hyannis d to re—esta	Cove was located blish its position.
The existing	the physical condition of the monument as found <u>brass disk in a Standard City Stra</u> d. & Hyannis Cove was found in go	eet Monument	well in the in	
construction	it was re—established and rebuilt S 8118" "Replaced by Corner Reco	with a 3" Alur		
	SURVEYOR'S STATEMENT Indicate the state of			RANDALL T. WILLIS OF PLS 8118 Exp. 12/31/10
	COUNTY SURVEYOR'S STATEMENT	٢	ŗ	OF CALIFORN

