
City of SAN RAFAEL County of MARIN Recorder's Document No. 09-028988 Same As Parcel E 21 OS 59 CORNER TYPE Government Corner Control Discourse No. 09-028988 Same As Parcel E 21 OS 59 CORNER TYPE Government Corner Control Discourse No. 09-028988 Same As Parcel E 21 OS 59 CORNER TYPE Recorder's Document No. 09-028988 Same As Parcel E 21 OS 59 CORDINATES (Optional) N
CORNER TYPE Government Corner
Government Corner
Identification and type of corner found. Evidence used to identify or procedure used to establish or recetablish the corner.
IRON PIPE MONUMENTS AS SHOWN ON 21 OS 59 WERE FOUND AT FOUR BOUNDARY CORNER AND AT THE NORTHEASTERLY AND SOUTHWESTERLY EXTENSION OF THE SOUTHEASTERLY BOUNDARY LINE. RECORD ANGLES AND DISTANCES WERE TURNED TO SET THE REMAINING FOUR LOT CORNERS.
A description and the physical condition of the monument as found and as set or reset: IRON PIPE MONUMENTS SHOWN ON 21 OS 59 WERE FOUND IN GOOD CONDITION. 3/4" IRON PIPES WITH TAG RCE 12094 WERE SET AT BOUNDARY CORNERS. SPIKES, MAG NAILS, AND 1"x2" STAKES WERE SET ALONG CURVED BOUNDARY LINES.
SURVETURS STATEMENT
This Corner Record was prepared by me or under my direction in conformance with \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
the Land Surveyor's Act on March 2010 Signed My P.L.S. of R.C.E. No. RCE 12094 OF CALIFORNIA
COUNTY SURVEYOR'S STATEMENT
This Corner Record was received MARCH 17, 2010
and examined and filed APRIL 6, 2010
Signed P.L.S. of R.C.E. No. 7128
Title COUNTY SURVEYOR
County Surveyor's Comment



Page 2 of 2