UH-1

MARIN COUNTY COMMUNITY DEVELOPMENT BLOCK GRANT (CDBG) PROPOSAL 2014-15

1. Project Name: Fairfax Vest Pocket

2. Total Amount Requested:
Non-housing proposals must

specify the amount requested from each planning area.

\$ 310, 573

3. Project Sponsor: Marin Housing Authority

Contact Person: Kimberly Carroll

Title: Deputy Executive Director

Mailing Address: 4020 Civic Center Drive

San Rafael, CA 94903

Telephone: 415-491-2348

Fax: 415-472-2186

E-mail: KCarroll@marinhousing.org

For non-housing projects only:	Funds
	Requested
Lower Ross Valley Planning Area	\$
Novato Planning Area	\$
Richardson Bay Planning Area	\$
San Rafael Planning Area	\$
Upper Ross Valley Planning Area	\$

Website (optional):

West Marin Planning Area

All future announcements will be sent to you by e-mail, unless you indicate otherwise: A Please send by mail.

Ext.

The County of Marin is committed to encouraging new grant applicants. Please call us at 473-6698 for advice about our requirements and what to emphasize in your application, and consider attending one of our informational workshops. HUD requires that all CDBG projects engage in affirmative marketing. That means analyzing which demographic groups are least likely to apply and taking extra steps to market the program or project to those groups. One aspect of affirmative marketing is implementing strategies to make your program more welcoming and comfortable to the groups which are least likely to apply. The goals of affirmative marketing are to enhance neighborhood diversity and to support the County's commitment to affirmatively furthering fair housing and equal opportunity.

The concept of fair housing encompasses both federal and state laws that prohibit housing discrimination. The federal Fair Housing Act prohibits discrimination in the sale, rental, and financing of dwellings, and in other housing-related transactions, based on race, color, national origin, religion, sex, familial status (including pregnancy and the presence of children), and disability. In addition, state law prohibits housing discrimination on the basis of age, ancestry, marital status, medical condition, source of income, sexual orientation, gender expression, gender identity, and many other categories.

4. Project Location: (Precise street address). For housing and capital projects, include the year the building was constructed and the Assessor's Parcel Number.

	fax Vest Pocket Co , 82 & 84 Park Road		Owner: Housing Authority of the County of			
	airfax, CA 94930		APN:	001-148-12 and 002-0	12-03	
Population:	Congregate living		Parking:	Each bldg. has a smal	l parking lot	
S	Single Parent with 1 c	hild	Year Built:	1996		
	Total of 19 bedroom uildings. Community Building a			Community Building co , kitchen and <i>Facilities</i>	ontaining	
Building	3 Frustruck	5 Frustruck	80 Park	82 Park*	84 Park	
. BR / BA	4 BR / 3 BA	3 BR / 2 BA	3 BR / 2 BA	4 BR / 3 BA	1 BR / 2 BA	4 BR / 3 BA

5. Project Description:

The Fairfax Vest Pocket Community houses seniors (62+), people with disabilities and single parents. The Vest Pocket community was envisioned as a model inter-generation, shared housing community, which would foster a sense of the support provided by an extended family.

The construction cost was over \$2 million and is funded by the Housing and Community Development (HCD) of California. The current loan and interest for this property is over \$3 million. MHA took over the ownership of this property after the non-profit, Innovative Housing closed in November 1996. The project is regulated under a HCD regulatory agreement to house very low and low income residents

There are five houses and a community building which has a studio apartment. Currently there are 15 households, 13 seniors and 2 single parents. All residents are extremely low income. The rents range from \$465.00 to 560.00 per month. MHA is working with HCD to begin to house a single family in the next vacant home; the family will be a Section 8 tenant based large family currently screened and eligible for the Section 8 program. Presently there are a total of 4 vacant units in two homes; the single hard to house family will be able to move in to the vacant unit by February 2014.

Due to the low rental income generated by this project there has not been funds to address the immediate physical needs to sustain and preserve this affordable housing project in Marin County. It is critical for the safety of these residents that the dry rot and waterproof repairs and replacements be addressed as soon as possible.

6. Total Project Cost: (Include all costs for this particular project regardless of source.)

Total Operating Revenue \$112,542
Operating Expenses
Administrative \$54,621
Utilities \$10,279
Maintenance \$19,322
Insurance, taxes, general expenses \$14,804
Replacement Reserve \$7,641

Total Operating Expenses \$106,667 Operating Income (loss) \$ 5,875

Non-operating revenue (expense)

Interest income \$ 1,127 Accrued interest expense on CD cash flow loan \$ (61,535)

Net loss \$ (54,484)

Long Term Debt (HCD Loan) \$2,051,161 Interest on Long-Term Debt (HCD Loan) \$971,351 Immediate Physical Needs/Rehab \$310,573

7. Project Budget for CDBG Funds:

Budget <u>must</u> include an itemized estimate of how you would spend the CDBG amount you are requesting, as accurate and comprehensive as possible. For example, land or building acquisition costs, construction costs, remodeling costs, architectural and engineering fees, salaries, administrative expenses, etc. For rehabilitation or construction projects, you must include a contractor's written bid or other equally reliable cost estimate, using Davis-Bacon wage rates if applicable. If your project includes residential rehabilitation, describe your plans to comply with federal lead paint regulations.

We are requesting a total of \$310,573 in CDBG funding to complete this repair and replacement work at Fairfax Vest Pocket Community- please see attached budget estimate of the work completed by Segue Construction. Also attached is the most recent physical needs assessment completed September 8, 2010.

Site Work/Landscaping Parking / Driveway paving 6 ea \$ 1,500 \$ 9,000 Seal and stripe. Include ADA markings for one space	
Parking / Driveway paving 6 ea \$ 1,500 \$ 9,000 Seal and stripe. Include ADA markings for one space	
	e. Include ADA markings for one space
Landscaping 0 ea \$ - \$ - Updgrade landscaping	
Entry Landings, Steps, Railings 2 ea \$ 36,383 \$ 72,765 Replace decks, wood stairs and railings at 75 Park and 82 Park	s, wood stairs and railings at 75 Park and 82 Park
Building Ext. / Envelope	
Dry rot Allowance 6 ea \$ 3,638 \$ 21,830 Dry rot allowance	ice
Roof gutters 1 ea \$ 6,064 \$ 6,064 Install leaf guards at buildings were trees are dropping debris	rds at buildings were trees are dropping debris
Trim and soffits 1 ea \$ 12,128 \$ 12,128 Allowance to address dry rot at eave support and roof soffits	address dry rot at eave support and roof soffits
Paint and waterproofing 6 ea \$ 10,915 \$ 65,489 Remove rust, renail if necessary, caulk and other prep, exterior paint	enail if necessary, caulk and other prep, exterior paint
Unit Interior Fixtures & Finishes	
Kitchen Cabinets 0 ea \$ 4,000 \$ - Replace per Matrix.	latrix.
Kitchen Counters 0 ea \$ 1,200 \$ - Replace per Matrix.	
Drywall Patch and Paint 0 ea \$ 1,819 \$ - Replace per Matrix. Repairs at bath fans, tub surrounds	latrix. Repairs at bath fans, tub surrounds
Kitchen Vinyl 0 ea \$ 970 \$ - Replace per Matrix.	latrix.
Refrigerators 0 ea \$ 650 \$ - Replace per Matrix.	
Stoves 0 ea \$ 675 \$ - Replace stoves per Maxtrix	s per Maxtrix
Range Hoods 0 ea \$ 250 \$ - Replace per Matrix.	Matrix.
Bathroom Vanity Cabinets and Tops 0 ea \$ 788 \$ - Replace per Matrix.	Matrix.
Carpet flooring 0 ea \$ 2,426 \$ - Replace per Matrix.	Matrix.
Bathroom Vinyl Flooring and Base 0 ea \$ 728 \$ - Replace per Matrix.	Matrix.
Tub and Shower Surrounds 0 ea \$ 1,455 \$ - Replace per Matrix.	Matrix.
Shower Valves 0 ea \$ 1,455 \$ - Allowance to reconfigure valves, new valves, plumbing config.	econfigure valves, new valves, plumbing config.
Toilets 0 ea \$ 728 \$ - Replace per Matrix.	Natrix.
Mechanical/Electrical	,
Forced air units 0 ea \$ 900 \$ - Reconfigure lines and install new heaters in units.	nes and install new heaters in units.
Water Heaters 0 ea \$ 700 \$ - Replace water heater at unit 14	r heater at unit 14
Bathroom exhaust fans 6 ea \$ 970 \$ 5,821 Replace old heat/light/fan units at ceilings	eat/light/fan units at ceilings
Exterior Light Fixtures 0 ea \$ 9,000 \$ - Building mounted lighting.	ited lighting.
Total Construction \$ 193,095	
Contingency 20% \$ 38,619	
Total Immediate Physical Needs \$ 231,715	
General Conditions \$ 50,000	
Insurance @1.05% \$ 3,261	/
Bond@1.7% \$ 5,280	
Overhead/Profit @7% \$ 20,318	
GRAND TOTAL \$ 310,573	

8. Other Sources of Funds for this Project: Include amount, source, use, status, and timing of funds other than CDBG funds, if applicable. Have you applied for the other funds? Are the other funds firmly committed for this project?

Date You Are Funds Date Funds Were When Source Use Amount Applied Committed? Committed Available N/A

9. Project Implementation:

Who will be responsible for implementing the project? How will it be implemented and what is the proposed schedule for project implementation?

Marin Housing staff will be responsible for implementing this project with a procured General Contractor. The work will begin as soon as the contractor is procured and funding confirmed. The projection of work commencing would be August 2014 with a completion date of November 2014.

10. Need for the Project:

A. Need Group

What groups or individuals will benefit from the project? What income level will you serve? How will you document eligibility? CDBG recipients are required to provide documentation that the majority of the users have incomes at or below the CDBG income limits. The current upper income limits for CDBG beneficiaries are shown in the table below. Applicants for housing funds must describe how the project will ensure long-term affordability.

Household	Income
Size	Limit
1	\$59,100
2	67,550
3	76,000
4	84,400
5	91,200
6	97,950
7	104,700
8	111,450

Since 1998, the program has specifically benefited very low-income renters. Every household assisted through the program has income well below 80% of median, currently (100%) are at or below 30% of AMI. The annual income for the13 household of one ranges from \$6,504 to the high of \$18,724; the two families with a household of two have incomes of \$20,712 and \$27,380. Eligibility is documented in a personal interview conducted with each applicant in which original pay stubs, assistance payments and all other sources of income are reviewed and copied to the file- the income is recertified annually. The current rent roll is attached; rents run \$457.00 to \$560.00.

The program ensures long term affordability as the project is under a HCD 30-year regulatory agreement. The project serves elderly and/or disabled and single parent households.

B. Project Rationale: Why is this project needed? Will it assist an especially needy or underserved group?

With continually escalating rental prices and the resulting decrease in affordable housing, the Fairfax Vest Pocket Community offers an affordable housing option in to senior, people with disabilities, families and those with poor credit or other barriers to housing. This housing is located in a good community, near good school, parks and bus lines. For the preservation of this housing it is critical to address the deferred maintenance physical repair upgrades at this property.

C. Equal Opportunity: For all projects, which demographic groups are least likely to apply, and what affirmative marketing steps do you plan to reach them? (Affirmative marketing means analyzing which demographic groups are least likely to apply and taking extra steps to market the program to those groups. One aspect of affirmative marketing is implementing strategies to make your program more welcoming and comfortable to the groups which are least likely to apply. Be sure to consider race, ethnicity, and disability, as well as other demographic factors, in your analysis.)

MHA is committed to affirmatively furthering fair housing. The responsibility to further non-discrimination pertains to all areas of MHA's operations. MHA has implemented a Language Assistance Plan to ensure marketing to non-English speaking sections of the population. MHA provides language interpretation services in over 150 languages and has translated critical documents into Spanish and Vietnamese. MHA has partnered with Fair Housing of Marin to provide on-going staff trainings and lunch and learn seminars. MHA has an assigned general counsel staff attorney serve as the 504 Coordinator; this staff ensures that all MHA departments are in compliances with Section 504 regulations. Additionally they handle all reasonable accommodation requests from program participants and related accessibility at agency owned facilities.

If this project involves housing, how will it affirmatively further fair housing?

Racial and ethnic minorities are underrepresented in the Fairfax Vest Pocket Community. Program applications and brochures are available in Spanish and Vietnamese as well as English and are disseminated through senior centers, community centers, Hispanic/Vietnams agencies, social service agencies and public libraries. Interpreters are also available on MHA staff and through a language assistance line.

By serving low-income households who are underrepresented in Marin County in this high-priced rental market. The Program furthers fair housing by providing the means for these renters to remain in Marin in affordable units

If this project involves construction, discuss (1) your plans for recruiting women- and minority-owned firms to bid on the design and development of this project, and (2) your plans to provide employment opportunities to low-income people and businesses owned by low-income people.

It is the policy of the Housing Authority that all contracts for supplies and services shall be in accordance with applicable Federal, State, and local laws and regulations. Established by Action of the MHA Board of Commissioners (Board) on July 19, 2011, this Procurement Policy (Policy) complies with the Federal Regulations at 24 CFR 85.36, the procurement standards of the Procurement Handbook for Public Housing Authorities (PHAs), HUD Handbook 7460.8, REV 2, and applicable State and Local laws.

The policy allows for a preference for a Section 3 business; Section 3 of the Housing and Urban Development Act of 1968 requires Marin Housing Authority to direct a portion of its spending toward low-income persons living in the communities it serves. One way Marin Housing Authority (MHA) achieves this goal is by awarding contracts to businesses that have made a commitment to providing opportunities to low-income persons in Marin County, this is done by providing Section 3 contractors with preferences in the procurement process.

For purposes of Marin Housing Authority, a Section 3 Resident is either:

- 1. A Marin Housing Authority public housing resident; OR
- 2. A Marin County resident with household income at or below 80% low income limits.

In addition for the procurement request for funding proposal process for this project, MHA will provide a preference on the procurement bid process for women and minority owned businesses

D. Accessibility: What steps are you taking to make this project (and your overall program) accessible to people with physical and other disabilities?

This project has been designed to serve people with physical disabilities; installation of fully accessible rooms and bathrooms have been installed in 5 of the 6 homes, the community room is also equipped with accessibility features. ADA parking space is being proposed for this project. MHA conducted a comprehensive needs assessment for persons with disabilities. A plan was developed to retrofit the units for accessibility for the mobility impaired in MHA's family and senior housing complexes. This assessment resulted in 15 family and 10 senior/disabled units being modified.

E. Green Building: For new construction or rehabilitation, what will you do to incorporate "green building" principles?

Whenever feasible, "green building" principles will be applied and implemented to assure the highest possible energy efficiency of the dwelling and the use of methods and materials least disruptive to the environment. All appropriate procurement will be conducted to incorporate the principles of energy efficiency reduction of global warming, transportation efficiency and minimum environmental impact.

- o For further information, please call Roy Bateman (473-6698). It's ok to call with any questions at any time.
- The current year's application form must be used.

- Completed applications may be mailed or hand-delivered to the Federal Grants Division, Marin County Community Development Agency, 3501 Civic Center Drive, Room 308, San Rafael, CA 94903-4157.
- Applications sent by fax or e-mail will not be accepted.
- This form can be expanded to accommodate additional text, but we encourage you to be brief. You may attach
 supplementary material. If you need more space for several questions, please answer all questions in sequence.
 If you'd like to download this form as a Microsoft Word document, visit www.marincdbg.com or
 www.co.marin.ca.us/depts/CD/main/comdev/FEDERAL/index.cfm.
- Don't forget to fill out the Organization Profile form.
- All County publications are available in alternative formats (Braille, large print, or CD) upon request. Requests for accommodations may be made by calling (415) 473-4381 (Voice), 473-3232 (TDD/TTY), or by e-mail at disabilityaccess@marincounty.org. This form and other County documents are available in alternative formats upon request.

DEADLINE: APPLICATIONS MUST BE RECEIVED BY FRIDAY, DECEMBER 13, 2013, AT 5 P.M.

Remember that we don't accept e-mailed or faxed applications.

K:\Cycle\2014 Cycle\Grant Applications\2014-15 CDBG Application Form.Doc/roy

SEGUE CONSTRUCTION, INC.



December 12, 2013

via email

Carmen Soruco Marin Housing Authority 4020 Civic Center Drive San Rafael, CA 94903

Re:

Fairfax Vest Pocket Community 75,80,82,84 Park Road 3,5 Frustruck Street Fairfax, CA

Dear Carmen:

Please find below a budget estimate for the immediate physical needs discussed.

ITEMS	QUANTITY	UNIT	UNI	тсост	то	TAL COST	COMMENTS	
Site Work/Landscaping								
Parking / Driveway paving	6	ea	\$	1,500	\$	9,000	Seal and stripe. Include ADA markings for one space	
Landscaping	0	ea	\$	-	69	-	Updgrade landscaping	
Entry Landings, Steps, Railings	2	ea	\$	36,383	\$	72,765	Replace decks, wood stairs and railings at 75 Park and 82 Park	
Building Ext. / Envelope								
Dry rot Allowance	6	ea	\$	3,638	\$	21,830	Dry rot allowance	
Roof gutters	1	ea	\$	6,064	\$	6,064	Install leaf guards at buildings were trees are dropping debris	
Trim and soffits	1	ea	\$	12,128	\$	12,128	Allowance to address dry rot at eave support and roof soffits	
Paint and waterproofing	6	ea	\$	10,915	\$	65,489	Remove rust, renail if necessary, caulk and other prep, exterior paint	
Unit Interior Fixtures & Finishes							(1-20)	
Kitchen Cabinets	0	ea	\$	4,000	\$	-	Replace per Matrix.	
Kitchen Counters	0	ea	\$	1,200	\$	-	Replace per Matrix.	
Drywall Patch and Paint	0	ea	\$	1,819	\$	-	Replace per Matrix. Repairs at bath fans, tub surrounds	
Kitchen Vinyl	0	ea	\$	970	\$	-	Replace per Matrix.	
Refrigerators	0	ea	\$	650	\$	-	Replace per Matrix.	
Stoves	0	ea	\$	675	\$	-	Replace stoves per Maxtrix	
Range Hoods	0	ea	\$	250	\$	-	Replace per Matrix.	
Bathroom Vanity Cabinets and Tops	0	ea	\$	788	\$	-	Replace per Matrix.	
Carpet flooring	0	ea	\$	2,426	\$	-	Replace per Matrix.	
Bathroom Vinyl Flooring and Base	0	ea	\$	728	\$	-	Replace per Matrix.	
Tub and Shower Surrounds	0	ea	\$	1,455	\$	-	Replace per Matrix.	
Shower Valves	0	ea	\$	1,455	\$	-	Allowance to reconfigure valves, new valves, plumbing config.	
Toilets	0	ea	\$	728	\$	-	Replace per Matrix.	
Mechanical/Electrical			Γ		Г			
Forced air units	0	ea	\$	900	\$	-	Reconfigure lines and install new heaters in units.	
Water Heaters	0	ea	\$	700	\$	-	Replace water heater at unit 14	
Bathroom exhaust fans	6	ea	\$	970	\$	5,821	Replace old heat/light/fan units at ceilings	
Exterior Light Fixtures	0	ea	\$	9,000	\$	-	Building mounted lighting.	
Total Construction		T	Т	manuscrate de la companya del companya de la companya del companya de la companya	\$	193,095		
Contingency	20%	T	T		\$	38,619		
Total Immediate Physical Needs	1		1		\$			
General Conditions		T	T		\$	50,000		
Insurance @1.05%	†	T	T		\$	3,261		
Bond@1.7%	†	+-	t^{-}		\$	5,280		
Overhead/Profit @7%	 	+-	+		\$	20,318		
GRAND TOTAL	 	+	+		\$			

SEGUE CONSTRUCTION, INC.

The above costs are based on non-prevailing wages. Please call should you have any questions.

Sincerely.

Steve W. Grider

PHYSICAL NEEDS ASSESSMENT

For

FAIRFAX VEST POCKET COMMUNITY 75, 80, 82, 84 PARK ROAD 3, 5 FRUSTRUCK STREET FAIRFAX, CA 94930

SEPTEMBER 8, 2010

Client: Marin Housing Authority 4020 Civic Center Drive San Rafael, CA 94903

(415) 491-2525

Attention: Marianne Lim, Sr. Project Manager

Prepared by: Elizabeth McLachlan Consulting 2370 Market Street, #189 San Francisco, CA 94114 415.203-8814 emclach@pair.com

TABLE OF CONTENTS

1. (OVI	ERVIEW	1
		Property Information	1
		Site Visit	2
		Statement Regarding Hazardous Materials	2
		No Conflict of Interest	2
		Inspection and Report Scope of Work	2
,		Green Building Recommendations	3
	١.	APARTMENTS INSPECTED	4
	3.	DOCUMENTS RECEIVED AND REVIEWED	
	PR	OPERTY CONDITIONS	5
	١.	IMMEDIATE ISSUES & CONCERNS:	5
	3.	GENERAL DESCRIPTION & CONDITIONS:	7
().	SITE CONSTRUCTION:	9
	1	. Soils Conditions:	9
	2	. Drainage/Topography	9
	3	Parking Areas & Driveways	10
	4	. Trash Collection	10
	5		11
	6		12
	7	. Entry Stairs, Entry Landings and Walkways	10
	8	Site Lighting	11
	9	. Accessibility	14
Г).	Building Construction	14
	1.	Structural and Foundation Systems	IO
	2	Ruiding Envolone: Exterior Walla	15
	3	J =	16
	4		17
			18
_	. 5. -	The state of the deal of the d	19
E	Ξ.	CONDITION OF BUILDING INTERIORS AND UNITS	19
	1.	The state of the s	19
	2		20
		a) Carpeting/ Resilient Flooring	20
		b) Appliances	21
		c) Cabinets/ Countertops	22
		d) Sinks/ Lavatories / Faucets	23
		e) Tubs & Shower Surrounds	24
		f) Shower Valves and Toilets	24
		f) Interior Doors and Framesh) Electrical Fixtures	25
		Interior walls / Ceilings	25
		j) Window Coverings/ Traverse Rods	∠b
		k) Painting	20 26
	3	. Common Areas / Maintenance / Utility	02 عد
	J.	a. Community Building	∠0
		b. Laundry Room	21 27
		C. Maintenance Shop	ረ <i>ነ</i> ጋያ
F		Mechanical Systems	20 20

1. Plumbing & Sewage Flow	28
2. Domestic Hot Water & Heating	28
3. Electrical	28
4. Mechanical Ventilation	28
5. Fire Alarm System / Emergency Systems	
APPENDIX A: IMMEDIATE PHYSICAL NEEDS	А
APPENDIX B: REPLACEMENT RESERVE	B
APPENDIX C: UNIT REPLACEMENT MATRIX	C

I. OVERVIEW

This Physical Needs Assessment (PNA) is prepared at the request of the Marin Housing Authority (MHA). The purpose of the report is to identify and document the building systems as conditions and to make recommendations for improvements.

How to Read this Report

This physical needs assessment report includes overview sections and immediate needs at the beginning of the document.

The estimated replacement spreadsheets (Immediate Needs, Reserve Study and Matrix) are located at the end of the report rather than embedded into the narrative report.

For those wishing to see only the *Immediate Physical Needs* and other summarized information, it is suggested that the reader cover Sections I and IIA+B only, then fast-forward to the spreadsheets located at the end, in the appendices.

This report includes photographs, which are best viewed on screen, rather than printed out.

Property Information

Project Name:	Fairfax Vest Pocket Community
Project Address:	75, 80, 82, 84 Park Road; 3, 5 Frustruck Street, Fairfax, CA
Property Manager:	EAH – has office in community building
Current Owner:	Marin Housing Authority
Date of Original Construction:	1996
Date of Last Rehab:	None
Number of Buildings:	6
Building Type:	Type V
Number of Units:	Total of 18 bedrooms, 7 kitchens and 15 baths in six buildings
Unit Mix:	75 Park – 3 bed/2 bath
	80 Park – 4 bed/3 bath
•	82 Park – Community building with 1/1 manager's unit
•	84 Park – 4 bed/3 bath
	3 Frustruck – 4 bed/2 bath
	5 Frustruck – 3 bed/2 bath
Total Building Area	21, 262 s.f.
Parcel Size:	Parcel 1: 18,423 s.f. (80, 82, 84 Park)
	Parcel 2: 16,500 s.f. (75 Park, 3, 5, Frustruck)
Assessor's Parcel ID:	002-012-03 and 001-148-12 Marin County
Common Areas and	Community building containing laundry room, kitchen and
Amenities:	community room + terrace
Parking:	Each building has a small parking lot with 3-5 spaces.
Building Construction	Wood framed structures. Foundations are slab on grade or
	foundation over crawlspace – depending on location.
Roof Construction	Asphalt shingle

Exterior Walls	Wood – board and batten sections, cementitious lap siding,
	plywood sections.
HVAC	Central forced air units
Fire/Life and Safety	Hard wired smoke detectors in bedrooms, hallways and living areas. Fire escapes at all building upstairs. Fire sprinklers and hard wired smoke detectors at community building. See recommendations in Fire Safety section at end of this report.
Present at inspections	Marianne Lim – Sr. Project Manager, MHA Dennis McCready – Maintenance Supervisor, MHA
Date of Inspections:	August 5, 2010
Weather on Date of	Partly cloudy
Inspections:	·

Site Visit

The property inspections were conducted on August 5, 2010. The above referenced persons accompanied Elizabeth McLachlan Consulting through the unit inspections.

The scope of the inspections consisted of a visual evaluation of the project site, buildings' exteriors, roofs (as seen from the ground), parking areas, driveways, community building and the interior spaces of all of the residential buildings. No detailed analyses or calculations were made to verify the adequacy of the building systems.

Statement Regarding Hazardous Materials

A Phase I Environmental Report was not available for review. Given the age of the building, it is unlikely that hazardous materials were used in the construction of the project. It is recommended that a Phase I study be conducted only if it is suspected that hazardous materials are present in or near the buildings. All findings and recommendations in any future Phase I report should be reviewed and performed as appropriate.

No Conflict of Interest

Elizabeth McLachlan Consulting certifies that no conflict of interest exists between it, the Sponsor, the management entity, contractors or subcontractors involved in the repair or rehabilitation of this project.

Inspection and Report Scope of Work

This report is based upon guidelines established by Fannie Mae. See Fannie Mae DUS guidelines: http://www.hud.gov/offices/hsg/omhar/readingrm/appendix/applattA.PDF and Fannie Mae Form 4327.

Access to all areas of the project was not available or not requested. For example, the roofs were not accessible and therefore they were not inspected. All specific observed equipment was not operated nor was there any specific formulaic tests conducted on any systems. No engineering or hazardous materials testing were done. No destructive or penetrative testing

was conducted. Damage to the systems and structures may be present although hidden and therefore could not be discovered without destructive testing. The observations and resulting report and recommendations do not give warranty nor do they guarantee the performance of any building components or systems.

This report does not provide <u>expert</u> opinions or recommendations on topics such as presence or absence of asbestos, lead, mold, wood destroying organisms, or soils conditions or toxicity on this property. This report does not provide expert opinions or details analyses on topics such as structural, mechanical, or architectural systems, nor is a comprehensive evaluation of building codes provided. If specific data and analysis for topics such as lead, asbestos, mold, soils, or structural or mechanical engineering are requested, the sponsor is encouraged to engage the services of respective qualified consultants.

This evaluation is based on the evaluator's observations and judgment of the physical condition of the improvements and estimated expected remaining useful life of those improvements. The actual performance of individual components may vary from a reasonably expected standard and may be affected by circumstances that occur after the date of evaluation. The evaluation is based on visual observations, exhibits reviewed and on comparable field experience.

Included with this report are:

- <u>This</u> narrative report containing information regarding systems and conditions as observed during inspections, along with discussion for each item.
- Immediate Physical Needs
- Replacement Reserve Study
- Unit Matrix

The cost estimates used in this report are based on approximate quantities and unit costs. They are also based on furnished information, which is assumed to be accurate.

Other estimated costs represent information depicted in published materials, previous reports and other reports for similar projects, estimates provided for similar and recent projects, estimating guides, such as RS Means Costworks, Dodge Guides, and others established by and/or used in the construction industry.

Elizabeth McLachlan Consulting bears no control over the costs of labor, materials, equipment or services provided by others; nor is there any control over competitive bidding procedures, or the methods of determining prices employed by others. Costs shown in this report incorporate industry averages, and the estimates are made based on this provider's experience. None of the costs used herein guarantee that proposals, bids, or costs will not vary. The project sponsor is strongly encouraged to seek out new bids for specific work, as appropriate.

Green Building Recommendations

Elizabeth McLachlan Consulting is a Certified Green Building Professional through Build It Green and has broad experience with green building systems, and has played a key role in the creation and evolution of "green PNAs" in the multifamily housing industry. Additional references and information can be provided upon request. Green/sustainable/energy efficient recommendations are weaved into the findings and recommendations of this report.

Recommendations made in this report are based on observations, and aim to include the most efficient replacement materials or methods possible. Recommendations also intend to include green building practices and recommendations for green rehabilitation for existing multifamily properties. Green references sources include: Build It Green's web site, LEED related publications. The publication *Green Rehabilitation of Multifamily Rental Properties*, is sourced for this report, where appropriate. ¹

A. APARTMENTS INSPECTED

In August 2010, the site and building exteriors were physically inspected to the extent possible, including the following specific elements: driveways and parking areas, concrete sidewalks, exterior and site lighting, site irrigation and drainage, exterior walls, roofing and roof drainage, mechanical, electrical and plumbing systems, and landscaping. The interiors of all buildings were inspected, however only 16 of the 18 bedrooms were inspected because one resident at 84 Park Road refused entry; a bedroom at 75 Park Road was locked.

B. DOCUMENTS RECEIVED AND REVIEWED

Exhibits Type	Document Name & Date		
Plans and Specifications	 Foundation details/plans (Sheets A6.2, S 2.4.0, S 2.5.0, S 2.6.0, S 2.7.0, S3.1) 		
	 As built Civil sheets (C1-C5) dated November 1995 		
	Landscaping plans dated 1991, Sheets L1-L2		
	 Construction Set dated February 7, 1995 (not complete set) 		
Preliminary Title Report	Not requested.		
List of Proposed Repairs	Misc. data points from MHA on recent or proposed		
	repairs.		
Phase I / Hazardous Materials Survey	None available		
Dry rot / Termite Inspection –	None available		
Property Inspection Reports –	None		
Name and Telephone Number of	Received		
Owner's Representative			
Estimates for current work being done	No formal bids or estimates were provided.		

¹ See, http://www.usgbc.org/DisplayPage.aspx?CMSPageID=1762, http://www.bayarealisc.org/bay_area/resources/publications_8392/green_10365/index.shtml

II. PROPERTY CONDITIONS

A. IMMEDIATE ISSUES & CONCERNS:

This project is in good condition overall and its location is excellent for residential living. Maintenance and management of the property appear to be fairly consistent and appear to be conducted on a regular and ongoing basis.

Based on the visual observations, the quality of the original construction is generally adequate. The property was constructed in 1996, making it nearly 15 years old – a time when major capital systems are reaching the end of their expected useful lives.

Issue & Description

Exterior Paint and Waterproofing

All buildings need to be painted at this time. When buildings are prepped, the rust from the siding nails should be removed. All caulk work should be done before painting is finalized.

Landscaping/Moisture Control

Updates to landscaping to make it more efficient are recommended in the immediate scope of work. Removal of plants that are growing too abundantly, such as the ivy at 5 Frustruck, is also recommended.

Electrical Wiring

GFCI receptacles for the bathrooms are apparently all on the same circuit inside the buildings. This should be altered so that each receptacle has its own breaker.

Parking Area Surfaces and Striping

The parking area should be sealed and striped in the immediate scope of work. All parking spaces need new striping, including a space designated as accessible.

Dry Rot - Decks and Railings

The wood decks that provide access to the fronts and side doors of some of the buildings are showing significant wear and dry rot. 75 Park's entry stairs are the worst of all and include a nosing board that is very loose. Porch railings at 75 Park are dry rotted and should be replaced.

Doors (exterior) and kitchen entrance doors

Exterior doors for trash containers at the 3 Frustruck building are damaged and need to be replaced. The entry doors off of the kitchens at 3 and 5 Frustruck stick slightly and maintenance should attend to the locks to see if replacements are needed or if the doors are out of alignment.

Wood destroying pests

A notable amount of dry rot was seen at the railings and at wood decking. Since the exterior surfaces are mostly wood, it is recommended that a wood destroying pests report be conducted.

Building Matrix Items

A replacement matrix is attached as Exhibit C to this report. It shows items that should be replaced in each building under the immediate scope of work. It also includes inspection notes taken during the August 5, 2010 inspections.

B. OVERVIEW OF GREEN BUILDING RECOMMENDATIONS


The following list provides a general overview of suggested green building recommendations for the Fairfax Vest Pocket Community. The recommendations are interspersed into relevant sections below.

- 1. Tier 1 approach (low hanging fruit):
 - Install low flow showerheads and faucet aerators.
 - Identify appliances that are near the end of their useful life and replace with Energy Star/Consortium for Energy Efficiency appliances (CEE) appliances (see, e.g., www.energystar.gov).
 - Lower hot water heating temperature to 120 degrees.
 - When roofs are replaced, consider using light colored shingles.
 - Create accessible and centralized recycling facilities on the property. Could be located behind 75 Park.
- 2. Tier 2 approach (broader recommendations):
 - Replace all windows and sliders with Low E double pane window assemblies. Replace the awning or casement windows because they not very energy efficient.
 - Use durable, long lasting exterior siding materials such as a cementitious fiber board product. The current board and batten siding wears easily and is subject to dry rot.
 - When siding is replaced, insulation should also be replaced using a cotton batt insulation, if needed.
 - Design and install exterior lighting that utilizes current high efficiency fixtures and shields the fixtures to prevent exterior lighting trespass. At present, the lighting is in good condition, but there may not be enough of it.
 - Conduct an Energy Audit to establish an accurate energy assessments prior to the completion of the project scope final work list.
 - Redesign and install native and adapted plants in the areas behind the buildings Most of the landscaping is well-thought out, but the use of water absorbing plants is also highly recommended because of the site drainage needs.
 - Replace some sections pavement at the Frustruck patios and courtyards with pervious materials. Install bioretention basins where applicable.
 - Eliminate potable water irrigation and use 100% harvested rain water. This project is well suited to harvesting rain water.
 - Install water efficient irrigation systems around building perimeter and create a testing and maintenance program for the systems.
 - Remove and replace a portion of the parking area surfaces with an open grid pavement system to promote storm water management and recharge of the below ground aquifers.
 - · Consider bamboo flooring for interior floor finishes.

- Replacement carpet should comply with CRI Green Label Plus Carpet Testing Program.
- Adhesives and Sealants used in Construction should comply with Low VOC limits as established in SCAQMD Rule #1168
- Paints should comply with VOC limits that comply with Green Seal Standard GS-11.
- All construction Materials should be harvested, manufactured, assembled and purchased within a 500 mile radius of the project site.
- Lumber that will be used on the project should be FSC Certified.
- All Exterior Trim Finishes should be either "Concrete Board" (Hardi Plank Materials) or Azek type trim materials
- Flush out all of the Interior spaces with fresh air at or above 60 degrees for a minimum of 48 hours prior to tenant occupancy.
- Install and Maintain Entry Way Mats to reduce dir, dust, pollen, and other particles from being tracked into the residences.

C. GENERAL DESCRIPTION & CONDITIONS:

The Fairfax Vest Pocket Community is a six-building community housing project located in Fairfax, California. The surrounding buildings are single and multi family residential structures. Commercial areas are located within 1/8 of a mile of the property. The area is ideal for residential living with quiet, tree lined streets and minimal vehicle traffic.



Aerial View of property. Buildings are marked with red address letters

All six buildings are two story, free standing structures containing 3 or 4 bedrooms each, full kitchens, three full bathrooms, living areas, dining areas and patios or yards.

Building information follows:

Address	Label	Total footprint	Beds	Baths	Remarks
5 Frustruck	Building 1	1932 s.f.	3 bed	2 bath	
80 Park	Building 2	2312 s.f.	4 bed	3 bath	
75 Park	Building 3	1932 s.f.	3 bed	2 bath	
84 Park	Building 4	2312 s.f.	4 bed	3 bath	
82 Park	Building 5	1827 s.f	1 bed	2 bath	Community
3 Frustruck	Building 6	2312 s.f.	4 bed	3 bath	

There are two parcels for this project. Each parcel contains three structures and each parcel is rectangular shaped.

Landscaping is abundant – some of it is native to the area, including trees and shrubs. Grass areas and plantings around the building perimeters are mostly maintained by the residents, although MHA does have a landscaping maintenance company.

The current condition of the building exteriors is fair because of the need for exterior paint and waterproofing.

Each building or building group has a small parking area containing 3-5 spaces each. Street parking is available in the immediate vicinity, though at the time of inspections, street parking was not abundant.

D. SITE CONSTRUCTION:

1. SOILS CONDITIONS:

A soils analysis was not available for review. The underlying geologic materials and topography may be a factor for evaluating structural conditions at the project. No unusual conditions were noted, however if unusual settling, erosion or drainage issues occur as a result of <u>soils</u>, it is recommended that the project sponsor conduct a civil engineering survey and/or structural survey. Any findings from a future civil or structural engineer's report, as relevant, should be incorporated into any major rehabilitation work.

The property is located in Zone AE (100 year flood zone), according to the Marin County (Fairfax) FEMA Flood Insurance Rate Map reviewed², therefore flood insurance may be specifically required by regulation in this region.

According to earthquake maps, the area in which this project lies is shown on relevant USGS maps. See, e.g., http://pubs.usgs.gov/sim/2005/2883/pdf/2883-1.pdf.

2. DRAINAGE/TOPOGRAPHY

Buildings located on Frustruck Street were built on a slightly upward sloping hill. The Park Road buildings are on relatively flat ground.

The project was inspected during a relatively dry summer so it was not possible to adequately assess drainage conditions. Small sections of the crawlspaces of the Frustruck buildings were observed and no evidence of water penetration or standing water was noted under the buildings. The maintenance supervisor did report that the Park Road buildings get a lot of water around them during rainy months. This is not unexpected given their situation. If the conditions result in detrimental or undesirable conditions – in other words, if water is entering the buildings during rainy periods, then it is necessary to create positive drainage to move water away from the buildings. It was noted on the reviewed drawings that drainage systems have been installed at the rear lot lines behind a few buildings.

Roof drainage occurs via gutters and downspouts, which terminate either into the subsurface drainage system or onto the landscaping (depending on location). Roof drainage is in


² FEMA flood mapping data as of 1981 survey. See, see http://msc.fema.gov/webapp/wcs/stores/servlet/FemaWelcomeView?storeId=10001&catalogId=10001&langId=1&userType=G)

adequate condition, however, again since the buildings were observed during a dry time, actual conditions of the roof drainage could not be assessed. Downspouts and gutters should be replaced in conjunction with future roof replacement.

Landscaping drainage occurs into the soils or into drains located in the landscaped areas. No problems were noted or reported with landscaping drainage. Drainage could not be observed "in action" since inspections were done at a very dry time of year.

3. PARKING AREAS & DRIVEWAYS

As mentioned, each building has a small parking area containing 3 to 5 parking spaces accessed by driveways. Each lot is paved with asphalt. Each lot contains a designated accessible parking space. Parking space striping is worn at every lot and striping should be redone in the immediate scope of work.



Parking lot at 75 Park Road

4. TRASH COLLECTION


Trash is collected at each building in exterior closets. Trash bins are moved to the street on collection days. No issues were noted with trash collection, however a couple of the exterior doors or closets could use replacements. Door and closet work is included in the Immediate Needs worksheet (Appendix A).

5. LANDSCAPING & IRRIGATION

Current landscaping consists of multiple types of shrubbery, ground cover and small sections of grass in front of a few buildings. Patios are covered with pavers and other plants provided by the residents. For the most part, landscaping takes into account the need for improved drainage by the use of pavers, pervious ground cover and appropriate shrubbery. The outdoor seating spaces, most notably behind the community building and in between 3 and 5 Frustruck are fairly well maintained.

A few landscaping upgrades are recommended in the immediate scope of work, including:

- Replace lawns with native grasses and/or drought resistant ground cover.
- All ground cover or earth sloping should be positive slope away from building footings.
- Remove ivy or other weed ground cover from behind 3 Frustruck. That type of foliage attracts rodents.
- Install rainwater harvesting systems in the below grade areas. Use collected water for irrigation. The harvesting system could include banks of rain collectors along the downspouts for the podium walkways. The harvested water can be used for irrigation.
- Cut back trees that overhang building roofs to prevent leaf debris into roof gutters or install gutter guards. Given the benefits of shade at this location, gutter guards are a much better choice to deal with leaf debris.
- Cure root growth which extends toward or into building bases/foundations.



Grass and shrubs at 84 Park Road

6. FENCING AND SITE SECURITY

There is no fencing around any of the buildings at Fairfax Vest Pocket. There are low retaining walls at a few of the properties (3, 5 Frustruck and 75 Park), which aid in soils erosion.

Security is not a major concern at this project. No issues of crime or vandalism were reported at the time of inspections. Therefore, installation of security devices is not recommended in the immediate scope of work.

7. ENTRY STAIRS, ENTRY LANDINGS AND WALKWAYS

Each building is entered via concrete or wood stairs. The architectural design of the 82 Park, 75 Park and 3 Frustruck buildings included the installation of wood stairs. These stairs, particularly at 75 Park, are in poor condition with loose boards and evidence of dry rot. The wood stairs should be replaced at 75 Park in the immediate scope of work. The use of Trex (though less attractive) may be beneficial and will last longer than wood. Alternatively, the stairs could be replaced with concrete or metal treads.

A few of the buildings contain porches and exterior walkways at the sides of them. Of these, 75 Park Road has a large wrap around porch that is in fair condition, except that the railings have significant dry rot. The railings should be replaced in the immediate scope of work.

The side deck at 3 Frustruck is in fair condition, some of the deck boards are loose.


The side deck at 5 Frustruck is in good condition.

The entry porch at 82 Park is in good condition, but the deck is getting slightly worn.

The entry stairs and landings at 84 and 80 Park Road and 3 Frustruck are concrete and were found to be in good condition.



Entry porch at 82 Park (Community Building)



Entry deck boards at 75 Frustruck. Nosing board is very loose.

8. SITE LIGHTING

Site lighting includes building mounted energy efficient lighting and city street lights. Exterior lighting appears to be in good condition although it was not operated during nighttime hours.

9. ACCESSIBILITY

The project was constructed in 1996, after the enactment of Federal ADA regulations. In 1992, the State of California adopted the Federal ADA regulations, with modifications as outlined in Chapters 10 and 11 of the CBC. Projects constructed after 1992 are to fully comply with the accessibility provisions prevailing at the time of building permit issuance. For publicly funded multifamily projects constructed prior to January 16, 1992, according to the Federal ADA standard (36.207 of 28 CFR Ch. 1), public accommodations are regulated, while individual apartment units are exempt. Essentially for existing buildings, the public accommodations and common use areas available to the residences and guests are to be modified to comply with the ADA standards when building permits are issued for new construction or for remodeling work. Such areas include parking stalls, path of travel from parking to the public recreational and project management office areas along with those same areas, exterior paths of travel within the project site, offices, common hallways, laundry, lobbies, community rooms, and similar common use areas (as they exist).

Accessible standards for existing projects are subject to the "hardship" rules. Updating portions of a project to meet current handicapped standards would be required under the current California Building Code when a general building permit is issued for any building improvements. This does not include repairs for deteriorated or building components damaged by fire or natural disasters. There are currently no units designated as "accessible" nor are any of the units truly "adaptable." The rehabilitation scope of work does not include any major alterations to the existing unit configurations, layouts or designs. If such alterations are posed, at least four units should be converted to accessible or to "adaptable." However, this recommendation is elective and will be determined by the sponsor.

The Municipality (city, county, et al.) may be authorized to issue a hardship variance on an individual basis should the construction improvements be valued at less than \$100,000, under which circumstance a maximum of 20% of the improvement value would be required to improve the path of travel and public accommodations. Improvements over \$100,000 are held by a different standard in that the 20% spending requirement is the floor, or minimum, rather than the maximum. Individual municipalities vary with regard to this financial hardship rule.

This report should not be considered an exhaustive evaluation of Federal ADA requirements. For purposes of the observations the ADA Accessible Guidelines for Buildings and Facilities (September 2002) is used as a guide (see: http://www.access-board.gov/adaag/html/ adaag.htm). The intent of this report is to provide a general overview of the accessible provisions, noting the obvious areas of non-compliance. If the above stated conditions exist for this project, the requirements will be invoked.

The Fairfax Vest Pocket Community has met most of the general common area accessibility requirements. If funding sources require it, or if it is believed that common area accessibility requirements are not being met, MHA should conduct an accessibility audit of the common areas at Fairfax Vest Pocket Community.

Downstairs bedrooms and bathrooms at each building are designated as accessible. All of the fixtures and finishes for accessible accommodations are in good to fair condition. Bathrooms are showing the most wear – with consistent need for tile grout and faucets. Kitchens at all buildings are generally accessible as far as maneuverability but no modifications have been made to appliances, electrical switches, cabinetry or counters.

Future modifications during rehabilitation should include the following general list of recommended updates and modifications for the accessible areas of each building, to the extent possible:

- The wall cabinets (kitchen, bath, hallway (if applicable)) should be lowered so that the bottom shelf is not higher than 48" above finish floor level. Alternatively, a shelf could be added above the kitchen counters where feasible to add accessible storage space. ADAAG Section 4.25.
- Where possible, the current "stacked" refrigerators should be replaced with side-by-side type models. ADAAG 9.2
- Ranges should have front mounted controls. ADAAG 9.2
- Lowering of door thresholds and transitions between finish flooring material to a maximum of ½" ADAAG 4.13.8.
- Widening of doors and the switching door swing to facilitate maneuverability. ADAAG 4.13
- Replacement of shower valves and faucets to fixtures that are operable with one hand and do not require tight grasping, pinching or twisting of the wrist. ADAAG 4.20.6
- Removal of sink base cabinets, and insulation of exposed p traps and hot water piping to avoid scalding.
- Installation of water closets with seats that are between 17" and 19" above finish flooring.
- Installation of a seat at the bathtubs or showers, which are mounted securely, and thus will not slip during use.
- Replacement of the shower unit with a fixture, which can be set at various heights, or as a hand-held shower with a hose at least 60" long.
- Add grab bars per ADA requirements or to the specific requirements of the apartment residents.
- Relocation of all controls (thermostats, switches) to appropriate heights (no higher than 48" for front approach- this applies primarily to the range hood controls)

E. BUILDING CONSTRUCTION

1. STRUCTURAL AND FOUNDATION SYSTEMS

The buildings were constructed in 1996, presumably in accordance with the building codes in effect at that time.

Architectural drawings were provided for review. A partial construction set dated February 7, 1995, Structural sheets dated June 1995 and other sheets (as noted above in Section A) were reviewed.


The residential buildings are Type V, single story buildings. 3, 5 Frustruck, 75 and 84 Park are foundation over crawlspace type foundation buildings. The other buildings are slab on grade

foundation or partial slab on grade with partial raised (depends on topography). All building perimeters have split rock façade with CMU masonry perimeter walls. Foundation footings, according to Sheet S2.4.0 are 4x6 posts located at 7" on center each way. Footings are 2'6" x 2'6"x12 thick at 4 #4 each way. Ledgers are shown as 3x10 pressure treated wood.


The crawlspaces of 3 and 5 Frustruck were observed (small areas of them), and no unusual conditions were noted at the building foundations or structures. Again, however, no destructive testing or inspections were conducted.

2. BUILDING ENVELOPE: EXTERIOR WALLS.


The exterior siding at the buildings is made of board and batten siding, wood panel siding (plywood) and cementitious fiber or wood composition siding. The condition of the siding is fair. All buildings have an immediate need for paint. Many of the buildings also show moderate rust from siding nailing. This is particularly true at the batten nails. When buildings are being prepped for painting, dry rotted materials need to be removed completely as they are found. Rust should be removed completely before painting. All penetrations, in particular nail holes, should be properly caulked and sealed before painting is completed.



Cracked lap siding at 84 Park Road



Rusted batten nailing at 82 Park Road



Rusted batten nailing at 75 Park


3. ROOF SYSTEMS

The buildings have 4:12 sloped roofs with asphalt shingle surfaces. All roofs are just 15 years

old and the sections that were observed show mild wear. No adverse conditions were noted at the roofs, except for one: there is a curious "lump" in the roof at 5 Frustruck (see photo). It looks like the roof was installed over the lump (which may be a vent pipe).

When roofs are replaced in the future, the gutters and downspouts should also be replaced. All roof penetrations will need to be reflashed/caulked when the roofs are replaced. All downspouts should terminate into concrete splashblocks or into the subsurface drainage, as appropriate for the locations.

When the buildings are painted, the wood eave support wood pieces need to be painted as well. Some of these, especially at 84 Park Road, show moderate cracking. It is not known if these eave supports are structural or decorative, but it is believed that they do provide some load support. Therefore, when roofs are replaced, these eave supports should be evaluated for dry rot or splitting – to determine if they need to be replaced.



Lump in roof at 5 Frustruck

4. WINDOWS & GLASS DOORS

The buildings are afforded a tremendous amount of natural light; they contain an abundance of windows. All windows are original to the project phases making them 15 years old. Each building contains a mixture of aluminum framed, dual paned: fixed pane, double hung and casement windows. The windows are dual paned and are energy efficient. Most windows are in fairly good condition.

When windows are replaced in the future, they should be insulated dual paned units with a low E-glass rating, which will improve the energy loss at the apartment units. Vinyl units should be used, or if aluminum replacement units are utilized, the window construction should include a thermal break, to prevent heat conduction through the metal frame. All operating windows should have screens. One current condition with the windows is that the casement windows have screens that are installed inside the windows. This setup is somewhat annoying because it means that the screens have to be removed in order to clean the windows.

Most buildings have wood framed glass doors that provide access to the front and rear of the buildings. These doors are in good condition except where noted in the Unit Matrix (Appendix C).

5. HAZARDOUS MATERIALS & WOOD DESTROYING PESTS

A Phase I Environmental report was not available for review. A Phase I study is not recommended in the immediate scope of work since the buildings are only 15 years old. If, in the future, hazardous materials are suspected in the surrounding areas, a Phase I study should be conducted. The findings and recommendations of the Phase I report should be included in any future rehabilitation scope of work, as appropriate.

A wood destroying pests report is recommended in the immediate scope of work given the amount of dry rot observed in specific areas.

F. CONDITION OF BUILDING INTERIORS AND UNITS

1. UNIT DESIGN AND OVERALL CONDITIONS

Each building has a solid wood entry door. Flooring at the buildings is wall to wall carpet at living rooms, stairs and upper hallways. Sheet vinyl flooring is installed at ground floor hallways, kitchens and dining areas.

Light fixtures in all buildings are primarily fluorescent ballast type with installed fixtures at kitchens, bathrooms and hallways.

The laminated kitchen cabinets in all units are original. All units have plastic laminated counter tops. The apartments have 30" free standing electric ranges, with ducted range hoods, dishwashers and two refrigerators.

Downstairs bathrooms at all buildings are accessible and contain tile flooring and showers, accessible shower valves and mixers, hanging sinks, and most have ADA compliant toilets. Upstairs bathrooms contains fiberglass shower surrounds and / or tub and shower surrounds. Each bathroom also contains a toilet, vanity cabinet, lavatory, medicine cabinet and towel racks. The showers contain mixing shower valves; when replaced, current code will require anti-scald device. An exhaust fan provides ventilation in the bathrooms.

Heating is provided to the buildings via central forced air units. All of the forced air units are original.

The average condition of the residential building interiors is good, and there are few issues to report. A few units were in need of serious housekeeping, a few units need to have bathroom

Ì

electric wiring rewired because GFCI outlets appear to be on the same circuit. A few bedrooms need carpet. All operated windows functioned as expected. Kitchens were typically dirty – with sticky floors and counters. Kitchens in these types of dwellings are the highly trafficked rooms so keeping them clean (and pest free) is imperative.

The Unit Matrix, appended to this report, provides unit by unit replacement recommendations as well as brief notes on each unit.

2. INTERIOR FIXTURES.


a) Carpeting/Resilient Flooring

The condition of the carpet and sheet vinyl or VCT flooring is generally good, except where noted on the Unit Matrix (Appendix C to this report). Existing carpet flooring is a cut pile or loop material with a medium density padding.

The resilient flooring at the units is also in good condition, except where noted. Older and, in some cases, original flooring was seen in some unit bathrooms.

When sheet vinyl is replaced in the future, it is recommended that a commercial sheet vinyl product should be used when replacing kitchen and bathroom floors, with a minimum 50 mil thickness which will hold up better in the long term. The manufacturer will guarantee replacement vinyl flooring for a minimum of five years. Bathrooms should continue to use sheet vinyl flooring. Vinyl composition tile or sheet vinyl flooring may be utilized at the kitchen areas. The use of bamboo flooring should be considered if funds are available since it is very durable material and it is typically harvested from sustained forests.


Replacement carpet should comply with HUD/FHA materials bulletin "UM44C," and carpet padding should comply with "UM72-80." Furthermore, Replacement carpet should comply with CRI Green Label Plus Carpet Testing Program.



Vinyl flooring at ground floor; carpet at stairs - typical

b) Appliances

The condition of the appliances in all buildings is good or fair. Stoves and range hoods are original, with refrigerators in some units having been replaced. Replacements for appliances are listed in the Unit Matrix.



Typical kitchen (84 Park Road shown)

All ranges are 30 inches in size and are manufactured by GE. All range hoods are manufactured by Broan.

Refrigerators are 17 or 18 cubic feet stacked models manufactured by Whirlpool. Energy Star rated refrigerators should be used for all future replacements.

Only a few units have garbage disposals and all of them are in poor condition. MHA's policy is to remove garbage disposals so the existing disposals should be removed and not replaced.

c) Cabinets/ Countertops


Cabinets are pressed wood or composition with laminate finishes. The average condition of cabinets is fair or good depending on housekeeping and wear.

Counter tops in all units are plastic laminate.

Bathroom vanity cabinets are similar in style to the kitchen cabinets.

Future cabinet replacements should comply with minimum cabinet specifications equivalent to WIC (Woodwork Institute of California) Custom Grade Specifications. Cabinets should be paint/stain grade wood, low or high-pressure laminates. Equivalent WIC Economy Grade cabinets are also acceptable.³

³ Source: Architectural Recommendations, 2008: http://www.calhfa.ca.gov/multifamily/financing/app-process/ArchitecturalRecommendations.pdf



Bathroom cabinet and sink

d) Sinks/ Lavatories / Faucets

The existing kitchen sinks are stainless steel dual bay units. Sinks should be replaced along with counter and cabinet replacements, as needed.

Faucets are primarily single handled models manufactured by Moen or Delta.


The bathroom sinks are original and are installed to sit on top of the vanity counters. All sinks were in fairly good condition except where noted on the unit matrix. A few units have dual sinks installed into the bathroom cabinets.

Downstairs bathrooms have hanging porcelain sinks, all of which were found to be in fair condition.

e) Tubs & Shower Surrounds

The finishes at the bathrooms with tubs and shower surrounds (the upstairs hallway bathrooms) are typically an enameled steel tub with tile surround. Most were found to be in good condition, however the tub and tile intersections need regular caulking.

The other upstairs bathrooms (found off a den area) contain fiberglass shower stalls with glass doors.



Tub surround and tub, mixer and spout. Typical.

f) Shower Valves and Toilets

The existing shower valves contain a mixing valve but they do not contain anti-scald mechanisms. Future replacements should include them. The diverter is located on the tub spout.

All of the installed toilets are low flow models – 1.2 to 1.6 gallon per minute devices.

f) Interior Doors and Frames

The interior doors within the residential units consist of paneled hollow core doors with Kwikset locksets. Closet doors are typically hollow core sliding type doors with top running tracks and bottom guides. All interior doors in the residential units were found to be in good condition.

h) Electrical Fixtures

The lighting fixtures are currently in good condition employing primarily fluorescent type fixtures. Kitchens and baths have fluorescent lights. Kitchen fixtures are dual tube lights with an opaque (light diffusing) cover. Bathroom over-vanity fixtures range from older fluorescent fixtures to newer fluorescent ballast (circline) type fixtures.

The bathrooms are mechanically ventilated with exhaust fans. These units are in fair condition and routine replacements are recommended. In properties such as these where is heavy bathroom traffic, it is recommended that humidistat devices be installed at the bathroom fans. These devices will ventilate the bathrooms until an acceptable moisture level is reached – thereby reduce moisture accumulation.

It is also recommended that the fans be on a separate switch from the light fixtures for all future replacements. Fan replacements have a maximum of 3.0 sones (measure of sound output), with enough power to provide a complete air change every fifteen minutes. A unit with a minimum capacity of 80 cubic feet per minute (cfm) is recommended.

GFCI receptacles were present in the kitchens and bathrooms. As will be discussed later in this report, bathrooms share a GFCI breaker. This should be split up and each GFCI should be on its own breaker. If two residents, for example, each use a hair dryer in separate bathrooms, the breaker will trip and both GFCIs will go offline.

Hard wired smoke detectors with battery backups are installed in all units.

ELIZABETH MCLACHLAN CONSULTING 415.203.8814



Typical ceiling fixtures at kitchen

Interior walls / Ceilings

The walls and ceilings are generally in good condition, except where noted in the Unit Matrix. No unusual cracks or staining was noted in any of the inspected apartments.

j) Window Coverings/ Traverse Rods

All units have vinyl vertical and horizontal blinds or drapery. Blinds were observed to be in good condition.

k) Painting

Painting occurs upon room or building turnover, but it is doubtful if units are painted while occupied. Typically, it is very difficult to paint an occupied unit. It is recommended, however, that any unit with flaking or damaged interior paint be re-painted as soon as feasible.

A semi-gloss paint should be utilized at the kitchen and bathroom walls so that the surfaces will be easier to wash. Preparation and cleaning procedures should be followed in strict accordance with paint manufacturer's recommendations for each particular substrate condition.

3. COMMON AREAS / MAINTENANCE / UTILITY

The common areas at the project include the community building and parking areas.

ELIZABETH McLachlan Consulting 415.203.8814

a. Community Building

The community building contains the laundry room, community room, community kitchen and offices for EAH and others. There is a patio at the rear of community building as well which provides a nice outdoor community space. The community room contains tables and chairs, couches, bookshelves and a television.



Community Room leading out to patio

The condition of the finishes at the community room is good and no updates are recommended.

The community room kitchen contains cabinetry and fixtures similar to the residential unit kitchens. No issues were noted with the kitchen.

There is a one-bedroom manager's unit at the upstairs portion of the community building. It was unoccupied at the time of this report.

b. Laundry Room

The laundry room is located just inside the main entrance to the community building. It contains three front loading washers and three dryers. It also contains a folding table. The laundry equipment is leased from Web (1-800-824-7780).

ELIZABETH MCLACHLAN CONSULTING 415.203.8814

C. Maintenance Shop

There is a maintenance room in the community building that contains cleaners and supplies, as well as the water heater, forced air unit and fire alarm equipment for the community building. There is too much stuff stored in the room and the toxic chemicals (e.g., fertilizer) need to be removed because they are flammable and because the room is not adequately ventilated.

G. MECHANICAL SYSTEMS

Mechanical drawings were not available for review in conjunction with this report.

1. PLUMBING & SEWAGE FLOW

Supply and waste lines are 15 years old. The plumbing supply for the property is copper. Finish plumbing in the units is brass (chromed, typical) for the trap and/or PVC in some locations. Waste piping is cast iron.

Common area plumbing is limited to hose bibbs and irrigation equipment). Any hose bibbs at the exteriors of the buildings should be fitted with anti-siphon devices to prevent the backflow of water into the domestic water supply.

2. DOMESTIC HOT WATER & HEATING

Each building has its own hot water heater and forced air unit. Hot water heaters are typically 50 gallon gas fired units. All water heaters, except for 5 Frustruck (new), are believed to be original. No maintenance records were provided for hot water heaters or heaters.

All of the forced air units are manufactured by York. No issues were reported with the heaters. Many of the observed heater vents were dirty and dusty. Duct cleaning is recommended in the immediate scope of work. Ducts should be cleaned at least annually.

3. ELECTRICAL

The apartment units are separately metered for electrical service. The meter banks are located in wood closets at the garages of each building. Each unit is supplied with a 60 amp capacity power. Load centers ("breaker boxes") are located at hallways or bedrooms inside the apartment units.

4. MECHANICAL VENTILATION

There are exhaust fans at the kitchens and bathrooms of all apartment units, as mentioned above.

Each building has a mechanical ventilator installed at the attic spaces. This "whole house fan" provides ventilation and cooling for the building. These units are incredibly efficient and replace air conditioning needs given the right location and climate. They are suitable for this project.

ELIZABETH McLachlan Consulting 415.203.8814

5. FIRE ALARM SYSTEM / EMERGENCY SYSTEMS

Each building contains hard wired smoke detectors with battery backups. Fire escapes are located in some of the upstairs rooms. The fire escapes located in bedrooms with locking doors present an egress issue since, if the bedroom is locked, there is not way to access the fire escape without breaking down the door. At 5 Frustruck, the fire escape upstairs is located in the bonus room between Rooms B and C. One side of this room is locked. Also, the window in this location is too high to provide an easy means of escape to the outside.

Family Housing Demonstration Program 2. Assisted Units incomes and Rents

STATE OF CAUPORNIA SCHEDULE OF RESTAL INCOME RHCP-8 AND FHÜP (Rev. 925/13)

(A)

		8			
	ProRata % Per	Regulatory Agreem	100.0%		Secember 31
Regulatory Agreement Total	Number of	Chita	19	2014	January 1 - C
Regulatory Agreement Number of Non-	Assisted	Chits	0	Fiscal Year:	art - Finish:
Regulatory Agreement Number of	Assisted	Cults	19		FY St.

				,			4	2001000				3			Regulatory							
MY	Jowances	ity Allowances (from Worksheet 1 Section B only)	1 Section B only)				5	oup by Unit S	(Group by Unit Size and by Very-Low and Lower Income Limit)	y-Low and Lo	wer income L	me)			Agreement	Regulatory						
il Stre er of B	it Size er of BPs	2013	2014		-					-				Agreement Number of	Number of Non-	Total		-				
p Home	eme	9	05											Assisted	Assisted	Number of	ProRata % Per	% Per				
SHO		55	30					County of: Martn	Wartn					Cults	Units	Unite	Regulatory Agreement	Greement				
Bdrm	-	\$					Contra	Contract Number: 9	93-FHDP-011					19	0	19	100.	8				
Bdrm	-	et.					Pro	lect Name:	Project Name: Fairfax Vest Pocket Community	ncket Commun	Á				Fiscal Year: 2014	2014						
Bdrm	-	\$	20				Spon	sor Name:	Sponsor Name: County of Marin	_			_	FY Sta	rt - Finish:	FY Start - Finish: January 1 - December 31	Secember 31					
Bdm	-	69					Managem	ent Agent:	Annegement Agent: EAH Housing				١	- 1								
Bdrm	-	68					E	Prepared By: C	0					2014	CPI Factor:	3.10%						
Bdrm	-	5	05				Date	Date Prepared: 9/18/2013	9/18/2013					Rent	Rent Adj. Factor:	8.00%						
	9	Ö	[0]	9	9	(9)	(H)	Ξ	5	K	E	[M]	M	[0]	[0]	Ō	(R)	<u>S</u>	E	2	2	Malwi
H			2013 Changes			2013	Current	2014	2013	2014	2014	2014	2014	2014	2014	2014	2014	2013	2014	2014	LEGEND of C	LEGEND of Compliance issues
-			Tallow Tenant or Vacant Sailti Subaldy		lingsene in the		Rent Rod's Net Rent	1	1	4			Sponsor			Crosses		Current like	American	-	P-RENT «Proposed rent is above for On-Valid income over income limit LIC=Nahid too sasal for 89R (under	P-RENT «Proposed rent is above formula Di-Hishig income over income limit JO-Hishig Inc gasal for 69% (under Occ.)
222 h E	Persons in	Number of Bedrooms/Terrested	N alto Change Had of Parsons Defle designation	Household	Marie No.	8	portion only. don't include		Gross Rent (Includes UA	No. of	Amount of Utility	Formula Maximum Allowatio	Rent (Tenant portion only, don't include	Approved Net Rent PHCD use	Monthly Rent Subsidy	Proposed Total Armed Tengra Rent	Annual Rent Successory	Paradicing Number of Horston at			D-Hehid too large 7 = HCD-approved A-Previous year of	DOMINIME In Inge for PER (over Occ.) AF = HCD-approved above formula rent AA=Fravious pear rent above approved
and the last	1	income Level	C-RINCP to-bom TCAC	Income	Income Level	Net Rents	substep)	Rent	flactel year!	Adjustment	8	\neg	IA or exheloy)	(Agent)	Amount	-Promised			E	-	splain compliance	Explain compliance issues in Column Y
_		2 BDWery Low	_	80	839,600	2484	\$465	0	\$465	\$37	8	2005	\$465	2098	8	\$6,580		8	88,024	\$6,024		ë
-	-	3 BD/Yery Low	_	\$13,440	\$39,600	2492	\$560	0	\$492	\$30	8	\$531	\$560	9006	8	\$6,720		S	\$7,260	\$7,260		UO; AF; AA
-	Co.	2 BD/Very Low	Z	\$17,363	\$45,250	\$583	\$560	0	\$560	845	8	\$605	3560	3008	8	86,720		S	\$7,260	\$7,260		
-	qu.	3 BD/Very Low	Z	\$11,100	\$39,600	\$484	\$465	0	\$465	237	8	\$502	\$465	\$502	8	\$5,580		90	\$6,024	\$6,024		ion
-	-	1 BD/Very Low	N	095,002	\$39,600	8476	\$457	0	\$457	237	8	\$494	\$457	2494	8	\$5,484		80	\$5,828	\$5,928		
-	2	1 BD/Very Low	N	\$13,212	\$45,250	\$484	\$465	0	\$466	\$37	8	2058	\$465	2098	8	\$5,580		8	\$6,024	\$6,024		
-		1 BD/Very Low	1	\$18,725	\$39,600	\$583	\$560	0	\$560	\$45	98	\$800	2560	\$606	8	\$6,720		8	\$7.260	\$7,280		
-		1 BD/Very Low	Z	\$10,967	\$39,600	\$484	\$465	0	\$465	103	88	\$505	\$465	2058	88	\$5,580		98	\$6,024	\$6,024		
-	-	2 BDWery Low	Z	\$18,048	\$39,600	2484	\$465	0	\$465	237	08	2095	\$465	2098	8	\$5.580		0\$	\$8,024	\$6,024		no:
-	-	2 BOWery Low	Z	\$6,804	\$39,600	\$583	\$580	0	\$560	245	8	3008	8560	\$000	8	\$6,720		0\$	\$7,260	87,260		no:
-	-	2 BDWery Low	1	88	839,600	\$484	\$465	0	\$466	237	98	\$502	\$465	2502	S	\$5,580		S	\$8,024	\$6,024		no:
H	-	3 BD/Very Low	Z	\$15,456	\$39,600	2484	\$465	0	\$466	\$37	8	\$505	2465	2098	98	\$5,580		8	\$6,024	\$6,024		ő
-	0	3 BDVery Low		98	\$45,250	2563	2500	0	\$560	\$45	8	\$606	8560	8608	8	\$8,720		8	\$7,260	\$7,260		ion
H	01	1 BDWery Low	1	80	\$45,250	2562	\$600	0	9560	\$45	8	9008	8560	\$606	8	\$6,720		8	\$7,260	\$7.280		
-	-	2 BDWery Low	Z	\$10,200	\$39,600	2464	2465	0	8465	\$37	8	2002	\$465	\$505	8	\$5,580		8	\$6,024	\$6,024		ion
-	61	2 BDWery Low	Z	\$20,712	845,250	2583	8560	0	\$560	848	90	9008	0995	\$605	8	\$6,720		S	\$7,260	\$7,260		
-	01	2 BDWery Low	z	\$11,160	\$45,250	2484	\$466	0	\$485	\$37	8	2058	\$465	8502	8	\$5,580		S	-	\$6,024		
H	c,	1 BDWery Low	Z	\$27,381	\$45,250	\$583	3360	0	\$560	\$45	8	3905	\$560	\$600	98	\$6,720		8	\$7,260	\$7,260		
H			TOTALS				\$9,122			\$724		88,778	58,122	\$9,862	8	\$109,464	8			\$110,224		
S.F	Subscoy		Total Assisted Units:		18																	
18	mmerts.																					
+	-			-	The same of the sa		-															

EAH Rent Roll Report

For the period 12-01-2013 to 12-31-2013

Fairfax Vest Pocket

-	dis	Loss/Gain to Lease	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
AlctoT	201	Total	502.00	605.00	560.00	502.00	494.00	502.00	605.00	465.00	502.00	605.00	0.00	465.00	0.00	0.00	500.00	465.00
		Over/Under	37.00	45.00	0.00	37.00	37.00	37.00	45.00	0.00	37.00	45.00	-465.00	0.00	-560.00	-560.00	0.00	0.00
		Vacancy	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	465.00	0.00	260.00	260.00	0.00	0.00
	Charges	Concessions	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
		Subsidy	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
		Tenant Rent	502.00 499.27	605.00	560.00	502.00 502.00	494.00	502.00	605.00	465.00 501.56	502.00 502.00	605.00	0.00	465.00	0.00	0.00	500.00	465.00
L		TCAC Max	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
		Contract Rent	465.00	260.00	260.00	465.00	457.00	465.00	260.00	465.00	465.00	260.00	465.00	465.00	560.00	260.00	200.00	465.00
		Unit	465.00	260.00	260.00	465.00	457.00	465.00	260.00	465.00	465.00	260.00	465.00	465.00	260.00	260.00	200.00	465.00
		Tenant	Spottedhorse	Benson	Harvey	Van Hook	Bourassa	SILBEY	Milner	Pederson	Weil	Blunt	VACANT	Rubin	VACANT	VACANT	Olney	Rossi
		Chrit	3-A	3-8	3°C	3-D	5-A	5-B	S-C	75-A	75-8	75-C	80-A	80-B	80-C	80-D	82	84-A

Over/Under = Tenant Rent + Subsidy + Concessions - Contract Rent Loss/Gain = Contract Rent - TCAC Max (or Market Rent if TCAC Max is 0)

200 1 000

EAH Rent Roll Report

For the period 12-01-2013 to 12-31-2013

Fairfax Vest Pocket

							Charges Receipts			. Tol	Totals
Unit	Tenant	Unit Rent	Contract	TCAC Max	Tenant Rent	Subsidy	Concessions	Vacancy	Over/Under	Total	Loss/Gain to Lease
84-8	Atwood-Pettit	260.00	560.00	0.00	605.00	0.00	0.00	0.00	45.00	605.00	0.00
84-C	VACANT	465.00	465.00	0.00	0.00	0.00	0.00	465.00	-465.00	0.00	0.00
84-D	Judson	560.00	560.00	0.00	605.00	0.00	0.00	0.00	45.00	605.00	0.00
Totals fo Pocket	Totals for Fairfax Vest Pocket	9,622.00	9,622.00	0.00	7,982.00	0.00	0.00	2,050.00	-1,640.00	7,982.00	0.00

EAH Rent Roll Report

For the period 12-01-2013 to 12-31-2013

GRAND TOTALS

		1.
Totals	Loss/Gain to Lease	0.00
Tot	Total	7,982.00
	Over/Under	2,050.00 -1,640.00
	Vacancy	
Charges Receipts	Concessions	00:00
	Subsidy	0.00
	Tenant Rent	7,982.00
	TCAC Max	0.00
	Contract Rent	9,622.00
	Unit Rent	9,622.00



December 13, 2013

4020 Civic Center Drive San Rafael, CA 94903-4173

> Executive Director Lewis Jordan

Roy Bateman, Community Development Coordinator Federal Grants Division Marin County Community Development Agency 3501 Civic Center Drive, Room 308 San Rafael, Ca 94903-4157

RE: Submittal of CDBG Grant Proposal for Fairfax Vest Pocket Community.

Marin Housing Authority (MHA) has submitted a proposal to the County for Community Development Block Grant (CDBG) funds for the Fairfax Vest Pocket Community for FY 2014/15 in the amount of \$310,573.

If awarded, funds will be used to address critical property repairs identified by a current physical needs assessment conducted for the Fairfax Vest Pocket Community project.

The Fairfax Vest Pocket Community affordable housing project houses very low income seniors (62+), people with disabilities and single parents in the town of Fairfax.

Sincerely,

Kimberly Carroll Deputy Director

Attachment: CDBG Proposal, Repair/Construction Budget, Physical Needs Assessment, Unit Incomes and Rents.

Housing Authority of the County of Marin

415/491-2525

(FAX) 415/472-2186 (TDD) 1-800-735-2929

www.marinhousing.org

			•

MARIN COUNTY COMMUNITY DEVELOPMENT **BLOCK GRANT (CDBG) PROPOSAL** 2014-15

2.

\$16,800

Project Name: San Anselmo Lifehouse 1.

Project Sponsor: Lifehouse

Contact Person: Brent Kush

Title: Director of Finance and Administration

Mailing Address: 899 Northgate Dr., Suite 500

San Rafael, CA 94903

Telephone: 472-2373

Ext.

Fax: 472-5379

E-mail: bkush@lifehouseagency.org

All future announcements will be sent to you by e-mail, unless you indicate otherwise:

Please send by mail.

Total Amount Requested:

Non-housing proposals must

specify the amount requested from each planning area.

For non-housing projects only:	Funds
	Requested
Lower Ross Valley Planning Area	\$
Novato Planning Area	\$
Richardson Bay Planning Area	\$
San Rafael Planning Area	\$
Upper Ross Valley Planning Area	\$
West Marin Planning Area	\$
Website (optional):	

The County of Marin is committed to encouraging new grant applicants. Please call us at 473-6698 for advice about our requirements and what to emphasize in your application, and consider attending one of our informational workshops. HUD requires that all CDBG projects engage in affirmative marketing. That means analyzing which demographic groups are least likely to apply and taking extra steps to market the program or project to those groups. One aspect of affirmative marketing is implementing strategies to make your program more welcoming and comfortable to the groups which are least likely to apply. The goals of affirmative marketing are to enhance neighborhood diversity and to support the County's commitment to affirmatively furthering fair housing and equal opportunity.

The concept of fair housing encompasses both federal and state laws that prohibit housing discrimination. The federal Fair Housing Act prohibits discrimination in the sale, rental, and financing of dwellings, and in other housing-related transactions, based on race, color, national origin, religion, sex, familial status (including pregnancy and the presence of children), and disability. In addition, state law prohibits housing discrimination on the basis of age, ancestry, marital status, medical condition, source of income, sexual orientation, gender expression, gender identity, and many other categories.

4. Project Location: (Precise street address). For housing and capital projects, include the year the building was constructed and the Assessor's Parcel Number.

1036 Sir Francisco Drake Blvd., San Anselmo, CA 94960

Parcel number: 006-632-09

This home is approximately 60 years old

5. Project Description:

This is an Independent Living Skills training home serving five adults with developmental disabilities. It is a unique home for individuals to increase the independence of the residents. It is an innovative home that was opened more than 20 years ago and is only one of a couple homes that provide this type of support for people with disabilities. Staff from Lifehouse provide the support the residents need to live in this type of situation and the residents have become very much a support to each other since they have lived together in the same household for many years.

- 6. Total Project Cost: (Include all costs for this particular project regardless of source.) \$16,800
- 7. Project Budget for CDBG Funds:

Budget must include an itemized estimate of how you would spend the CDBG amount you are requesting, as accurate and comprehensive as possible. For example, land or building acquisition costs, construction costs, remodeling costs, architectural and engineering fees, salaries, administrative expenses, etc. For rehabilitation or construction projects, you must include a contractor's written bid or other equally reliable cost estimate, using Dayis-Bacon wage rates if applicable. If your project includes residential rehabilitation, describe your plans to comply with federal lead paint regulations.

- 1. Clear each room of all personal articles and furniture. 2. Install ¼ sheetrock over asbestos popcorn celing. 3. Tape, mud, texture rock. 4. Prime room with 2 coats of sealer. 5. Spray two coats of finish latex paint whole room. Process will seal problem areas 100% from popcorn ceiling and avoid contact with material
- **8. Other Sources of Funds for this Project:** *Include amount, source, use, status, and timing of funds other than CDBG funds, if applicable. Have you applied for the other funds? Are the other funds firmly committed for this project?*

			Date You	Are Funds	Date Funds Were	When
<u>Source</u>	<u>Use</u>	<u>Amount</u>	Applied	Committed?	Committed	<u>Available</u>
None						

9. Project Implementation:

Who will be responsible for implementing the project? How will it be implemented and what is the proposed schedule for project implementation?

Lifehouse administrative staff wil work with a contractor to schedule the work. Bids will be obtained and the lowest/most qualified bid will be awarded. The project should take approximately one week to complete.

10. Need for the Project:

A. Need Group

What groups or individuals will benefit from the project? What income level will you serve? How will you document eligibility? CDBG recipients are required to provide documentation that the majority of the users have incomes at or below the CDBG income limits. The current upper income limits for CDBG beneficiaries are shown in the table below. Applicants for housing funds must describe how the project will ensure long-term affordability.

Household	Income
Size	Limit
1	\$59,100
· 2	67,550
3	76,000
4	84,400
5	91,200
6	97,950
7	104,700
8	111,450

There are five adults living in this home, many of whom have been housemates for more than 15 years. The individuals who live here are all in the category of "extremely low income". They receive MediCal. There is a rent subsidy through Marin Housing Authority due to their low income status. The home is owned by Lifehouse, a non-profit agency providing residential services to adults with developmental disabilities in Marin County.

- B. <u>Project Rationale:</u> Why is this project needed? Will it assist an especially needy or underserved group? Funding for all projects has been negatively affected by the economic downturn and also the cuts and frozen rates from the state for the services provided by Lifehouse. There have not been funds to make needed repairs.
- C. Equal Opportunity: For all projects, which demographic groups are least likely to apply, and what affirmative marketing steps do you plan to reach them? (Affirmative marketing means analyzing which demographic groups are least likely to apply and taking extra steps to market the program to those groups. One aspect of affirmative marketing is implementing strategies to make your program more welcoming and comfortable to the groups which are least likely to apply. Be sure to consider race, ethnicity, and disability, as well as other demographic factors, in your analysis.)

The residents of this home are referred by the regional center/state of California. Lifehouse has a policy of nondiscrimination in who it serves. The residents in this home must have a diagnosis of a disability to receive services.

If this project involves housing, how will it affirmatively further fair housing?

The individual who live here all have disabilities and are considered extremely low income. The home will always house people from this population.

If this project involves construction, discuss (1) your plans for recruiting women- and minority-owned firms to bid on the design and development of this project, and (2) your plans to provide employment opportunities to low-income people and businesses owned by low-income people.

Lifehouse does not discriminate in the selection of contractors. In recruiting contractors, minorities are always considered.

D. Accessibility: What steps are you taking to make this project (and your overall program) accessible to people with physical and other disabilities?

The individuals living in this home all have disabilities including a blind resident and others with physical disabilities

- E. <u>Green Building:</u> For new construction or rehabilitation, what will you do to incorporate "green building" principles? A consultant on "green" construction will be consulted and all available materials will be used to accomplish "green" objectives. Lifehouse as the owner is a non-profit agency.
 - o For further information, please call Roy Bateman (473-6698). It's ok to call with any questions at any time.
 - The current year's application form must be used.
 - Completed applications may be mailed or hand-delivered to the Federal Grants Division, Marin County Community Development Agency, 3501 Civic Center Drive, Room 308, San Rafael, CA 94903-4157.
 - Applications sent by fax or e-mail will not be accepted.
 - This form can be expanded to accommodate additional text, but we encourage you to be brief. You may attach supplementary material. If you need more space for several questions, please answer all questions in sequence. If you'd like to download this form as a Microsoft Word document, visit www.marincdbg.com or www.co.marin.ca.us/depts/CD/main/comdev/FEDERAL/index.cfm.
 - Don't forget to fill out the Organization Profile form.
 - All County publications are available in alternative formats (Braille, large print, or CD) upon request. Requests for accommodations may be made by calling (415) 473-4381 (Voice), 473-3232 (TDD/TTY), or by e-mail at disabilityaccess@marincounty.org. This form and other County documents are available in alternative formats upon request.

DEADLINE: APPLICATIONS MUST BE RECEIVED BY FRIDAY, DECEMBER 13, 2013, AT 5 P.M.

Remember that we don't accept e-mailed or faxed applications.

K:\Cycle\2014 Cycle\Grant Applications\2014-15 CDBG Application Form.Doc/roy

MARIN COUNTY COMMUNITY DEVELOPMENT **BLOCK GRANT (CDBG) PROPOSAL** 2014-15

1. **Project Name: Lifehouse HVAC** **Total Amount Requested:**

Non-housing proposals must

specify the amount requested from each planning area.

For non-housing projects only:

\$6,300

Funds

Project Sponsor: Lifehouse

Contact Person: Brent Kush

Title: Director of Finance and Administration

Mailing Address: 899 Northgate Dr., Suite 500

San Rafael, CA 94903

commitment to affirmatively furthering fair housing and equal opportunity.

Telephone: 472-2373

Ext.

Fax: 472-5739

E-mail: bkush@lifehouseagency.org

All future announcements will be sent to you by e-mail, unless you indicate otherwise:

□ Please send by mail.

Requested Lower Ross Valley Planning Area \$ Novato Planning Area \$ Richardson Bay Planning Area \$ San Rafael Planning Area \$ Upper Ross Valley Planning Area \$ 1,400 West Marin Planning Area \$ Website (optional):

The County of Marin is committed to encouraging new grant applicants. Please call us at 473-6698 for advice about our requirements and what to emphasize in your application, and consider attending one of our informational workshops. HUD requires that all CDBG projects engage in affirmative marketing. That means analyzing which demographic groups are least likely to apply and taking extra steps to market the program or project to those groups. One aspect of affirmative marketing is implementing strategies to make your program more welcoming and comfortable to the groups which are least likely to apply. The goals of affirmative marketing are to enhance neighborhood diversity and to support the County's

The concept of fair housing encompasses both federal and state laws that prohibit housing discrimination. The federal Fair Housing Act prohibits discrimination in the sale, rental, and financing of dwellings, and in other housing-related transactions, based on race, color, national origin, religion, sex, familial status (including pregnancy and the presence of children), and disability. In addition, state law prohibits housing discrimination on the basis of age, ancestry, marital status, medical condition, source of income, sexual orientation, gender expression, gender identity, and many other categories.

4. Project Location: (Precise street address). For housing and capital projects, include the year the building was constructed and the Assessor's Parcel Number.

All properties owned by Lifehouse. 1) & Seminole, Corte Madera 2) 16 Porteous Ave, Fairfax 3) 2 Stonehaven Ct., Novato 4) 210 Laurel Place, San Rafael 5) 593 Montecillo Rd., San Rafael 6) 393 Nova Albion, San Rafael 7) 1032 Sir Francis Drake Blvd., San Anselmo 8) 627 Wilson Ave., Novato 9) 48 Golden Hinde Blvd., San Rafael

5. Project Description:

Installation of wireless HVAC thermostats in each house for better energy conservation. Cost is \$700 per house. Aim of project is to maintain comfortable temperature control at each house while conserving energy usage in each home. The residents are often not at home during the day unless they are sick or unable to attend their day program. The temperature could be set wirelessly by house managers without making a trip to each house. The wireless units will allow for better control of costs and energy usage. The cost is an important factor to Lifehouse as the owner of the property since this is a non-profit agency.

Total Project Cost: (Include all costs for this particular project regardless of source.) \$6,300

7. Project Budget for CDBG Funds:

Budget must include an itemized estimate of how you would spend the CDBG amount you are requesting, as accurate and comprehensive as possible. For example, land or building acquisition costs, construction costs, remodeling costs, architectural and engineering fees, salaries, administrative expenses, etc.

1,400

If this project involves housing, how will it affirmatively further fair housing?

Lifehouse does not discriminate in the selection of contractors. Efforts are made to recruit minority businesses.

The individual who live here all have disabilities and are considered extremely low income. The home will always house people from this population.

If this project involves construction, discuss (1) your plans for recruiting women- and minority-owned firms to bid on the design and development of this project, and (2) your plans to provide employment opportunities to low-income people and businesses owned by low-income people.

Lifehouse does not discriminate in the selection of contractors. In recruiting contractors, minorities are always considered.

D. Accessibility: What steps are you taking to make this project (and your overall program) accessible to people with physical and other disabilities?

These homes are already occupied with individuals with disabilities and will continue to be used for this purpose.

E. <u>Green Building:</u> For new construction or rehabilitation, what will you do to incorporate "green building" principles? A consultant on "green" construction will be consulted and all available materials will be used to accomplish "green" objectives.

A consultation "green' construction will be consulted and all available materials will be used to accomplish "green' objectives. Lifehouse as the owner is a non-profit agency.

- o For further information, please call Roy Bateman (473-6698). It's ok to call with any questions at any time.
- The current year's application form must be used.
- Completed applications may be mailed or hand-delivered to the Federal Grants Division, Marin County Community Development Agency, 3501 Civic Center Drive, Room 308, San Rafael, CA 94903-4157.
- Applications sent by fax or e-mail will not be accepted.
- This form can be expanded to accommodate additional text, but we encourage you to be brief. You may attach supplementary material. If you need more space for several questions, please answer all questions in sequence. If you'd like to download this form as a Microsoft Word document, visit www.marincdbg.com or www.co.marin.ca.us/depts/CD/main/comdev/FEDERAL/index.cfm.
- o Don't forget to fill out the Organization Profile form.
- All County publications are available in alternative formats (Braille, large print, or CD) upon request. Requests for accommodations may be made by calling (415) 473-4381 (Voice), 473-3232 (TDD/TTY), or by e-mail at disabilityaccess@marincounty.org. This form and other County documents are available in alternative formats upon request.

DEADLINE: APPLICATIONS MUST BE RECEIVED BY FRIDAY, DECEMBER 13, 2013, AT 5 P.M.

Remember that we don't accept e-mailed or faxed applications.

For rehabilitation or construction projects, you must include a contractor's written bid or other equally reliable cost estimate, using Davis-Bacon wage rates if applicable. If your project includes residential rehabilitation, describe your plans to comply with federal lead paint regulations.

- 1. Install wireless HVAC thermostats in each house for better energy conservation.
- 2. Cost per unit of \$700 for each of 9 properties owned by Lifehouse, a non-profit agency service people with disabilities.

3

8. Other Sources of Funds for this Project: Include amount, source, use, status, and timing of funds other than CDBG funds, if applicable. Have you applied for the other funds? Are the other funds firmly committed for this project?

Date You Are Funds Date Funds Were When Source None Amount Applied Committed? Committed Available

9. Project Implementation:

Who will be responsible for implementing the project? How will it be implemented and what is the proposed schedule for project implementation?

Funding for all projects has been negatively affected by the downturn in the economy. Over this period the state has cut and frozen rates paid to service provider agencies such as Lifehouse. There have not been funds to make needed repairs.

10. Need for the Project:

A. Need Group

What groups or individuals will benefit from the project? What income level will you serve? How will you document eligibility? CDBG recipients are required to provide documentation that the majority of the users have incomes at or below the CDBG income limits. The current upper income limits for CDBG beneficiaries are shown in the table below. Applicants for housing funds must describe how the project will ensure long-term affordability.

Household	Income
Size	Limit
1	\$59,100
2	67,550
3	76,000
4	84,400
5	91,200
6	97,950
7	104,700
8	111,450

Lifehouse provides residential services for 50 adults with developmental disabilities in these 9 homes in Marin County. In some cases, the residents themselves have to pay for utilities. All 50 residents are considered as "extremely or very low income". Lifehouse pays for the utilities in the other homes. Lifehouse is a non-profit agency which needs to find every possible way to conserve on costs since reimbursement from the state for their serves has been frozen and cut in the past few years. In addition to conserving on the cost of utilities, there would be less need for staff to make a trip to homes to turn down utilities when everyone has left the home during the day. Wireless units can maintain better control of the temperature at all times in the home.

B. <u>Project Rationale:</u> Why is this project needed? Will it assist an especially needy or underserved group? It is extremely important to maintain a specific temperature in these homes as the residents have disabilities and several have medical conditions which would require them to have the correct temperature in the home. It does affect their health and comfort. It is also a requirement of the homes with a state license.

Funding for all projects has been negatively affected by the economic downturn and also the cuts and frozen rates from the state for the services provided by Lifehouse.

C. <u>Equal Opportunity:</u> For all projects, which demographic groups are least likely to apply, and what affirmative marketing steps do you plan to reach them? (Affirmative marketing means analyzing which demographic groups are least likely to apply and taking extra steps to market the program to those groups. One aspect of affirmative marketing is implementing strategies to make your program more welcoming and comfortable to the groups which are least likely to apply. Be sure to consider race, ethnicity, and disability, as well as other demographic factors, in your analysis.)

The residents of this home are referred by the regional center/state of California. Lifehouse has a policy of non-discrimination in who it serves.

	,			
			•	

MARIN COUNTY COMMUNITY DEVELOPMENT BLOCK GRANT (CDBG) PROPOSAL 2014-15

UH-4

1. Project Name: Fairfax

2. Total Amount Requested:

Non-housing proposals must

specify the amount requested from each planning area.

\$80,000

3. Project Sponsor: Lifehouse

Contact Person: Brent Kush

Title: Director of Finance and Administration

Mailing Address: 899 Northgate Dr., Suite 500

San Rafael, CA 94903

Telephone: 472-2372

Ext.

Fax: 472-5739

E-mail: bkush@lifehouseagency.org

For non-housing projects only:	Funds
- 1	Requested
Lower Ross Valley Planning Area	\$
Novato Planning Area	\$
Richardson Bay Planning Area	\$
San Rafael Planning Area	\$
Upper Ross Valley Planning Area	\$
West Marin Planning Area	\$
188 B 14 4 4 1 11	

Website (optional):

All future announcements will be sent to you by e-mail, unless you indicate otherwise:

□ Please send by mail.

The County of Marin is committed to encouraging new grant applicants. Please call us at 473-6698 for advice about our requirements and what to emphasize in your application, and consider attending one of our informational workshops. HUD requires that all CDBG projects engage in affirmative marketing. That means analyzing which demographic groups are least likely to apply and taking extra steps to market the program or project to those groups. One aspect of affirmative marketing is implementing strategies to make your program more welcoming and comfortable to the groups which are least likely to apply. The goals of affirmative marketing are to enhance neighborhood diversity and to support the County's commitment to affirmatively furthering fair housing and equal opportunity.

The concept of fair housing encompasses both federal and state laws that prohibit housing discrimination. The federal Fair Housing Act prohibits discrimination in the sale, rental, and financing of dwellings, and in other housing-related transactions, based on race, color, national origin, religion, sex, familial status (including pregnancy and the presence of children), and disability. In addition, state law prohibits housing discrimination on the basis of age, ancestry, marital status, medical condition, source of income, sexual orientation, gender expression, gender identity, and many other categories.

4. **Project Location:** (<u>Precise</u> street address). For housing and capital projects, include the year the building was constructed and the Assessor's Parcel Number.

Address: 16 Porteos Ave/, Fairfax, CA 94030

Parcel number: 002-034-05

This home is approximately 80 years old.

5. Project Description:

This is a project to convert an existing separate double garage into a living unit for one or two individuals with disabilities or to rent to staff of Lifehouse for "work force" housing. The garage will be converted into a one bedroom or a large studio cottage with complete separation of utilities from the main house which is a home for six adults with developmental disabilities.

Total Project Cost: (Include all costs for this particular project regardless of source.)
 \$80,000

7. Project Budget for CDBG Funds:

Budget <u>must</u> include an itemized estimate of how you would spend the CDBG amount you are requesting, as accurate and comprehensive as possible. For example, land or building acquisition costs, construction costs, remodeling costs, architectural and engineering fees, salaries, administrative expenses, etc. For rehabilitation or construction projects, you must include a contractor's written bid or other equally reliable cost estimate, using Davis-Bacon wage rates if applicable. If your project includes residential rehabilitation, describe your plans to comply with federal lead paint regulations.

1. Existing structure will require new electrical service, a new water service, and a new sewer service.

- 2. The unit will be designed to allow for either a one bedroom or studio unit of approximately 20 X 20 foot size. 3. Cost figured at \$200 per square foot.
- **8. Other Sources of Funds for this Project:** *Include amount, source, use, status, and timing of funds other than CDBG funds, if applicable. Have you applied for the other funds? Are the other funds firmly committed for this project?*

			Date You	Are Funds	Date Funds Were	When
Source	<u>Use</u>	<u>Amount</u>	Applied	Committed?	Committed	<u>Available</u>
None						

9. Project Implementation:

Who will be responsible for implementing the project? How will it be implemented and what is the proposed schedule for project implementation?

Lifehouse administrative staff will work with a contractor to schedule the work. Bids will be obtained and the lowest/most qualified bid will be awarded. The project should take approximately three months to complete

10. Need for the Project:

A. Need Group

What groups or individuals will benefit from the project? What income level will you serve? How will you document eligibility? CDBG recipients are required to provide documentation that the majority of the users have incomes at or below the CDBG income limits. The current upper income limits for CDBG beneficiaries are shown in the table below. Applicants for housing funds must describe how the project will ensure long-term affordability.

Household	Income
Size	Limit
1	\$59,100
2	67,550
3	76,000
4	84,400
5	91,200
6	97,950
7	104,700
8	111,450

There are two possibilities for this rental cottage. One would be for an individual or a couple with disabilities to live in their own place which would not be a licensed home. It would be for adults capable of living in their own home with supported living services provided by Lifehouse, a non-profit agency supporting adults with developmental disabilities. A second possibility would be for the cottage to be used by a staff person of Lifehouse. Due to the high cost of living in Marin County, many staff of Lifehouse agency find they have to live out of county and commute. It is often difficult for Lifehouse to recruit qualified staff and this would be a bonus in recruitment. Lifehouse would look at the situation and determine whether the need was greater for adults with disabilities or for "work force" housing and then rent to people in either category.

- B. <u>Project Rationale:</u> Why is this project needed? Will it assist an especially needy or underserved group? Funding for all projects has been negatively affected by the economic downturn and also the cuts and frozen rates from the state for the services provided by Lifehouse. While there has been a demonstrated need for this type of housing, there have not been funds to make needed repairs.
- C. Equal Opportunity: For all projects, which demographic groups are least likely to apply, and what affirmative marketing steps do you plan to reach them? (Affirmative marketing means analyzing which demographic groups are least likely to apply and taking extra steps to market the program to those groups. One aspect of affirmative marketing is implementing strategies to make your program more welcoming and comfortable to the groups which are least likely to apply. Be sure to consider race, ethnicity, and disability, as well as other demographic factors, in your analysis.)

The residents of this home are referred by the regional center/state of California. Lifehouse has a policy of non-discrimination in who it serves.

If this project involves housing, how will it affirmatively further fair housing?

Whether this unit is rented to a person with a disability or someone working with this population, in either case, they will be considered low income by the AMI of Marin County.

If this project involves construction, discuss (1) your plans for recruiting women- and minority-owned firms to bid on the design and development of this project, and (2) your plans to provide employment opportunities to low-income people and businesses owned by low-income people.

Lifehouse has a policy of non-discrimination when it comes to contracting work. In recruiting contractors, minorities are always considered.

- D. Accessibility: What steps are you taking to make this project (and your overall program) accessible to people with physical and other disabilities?
- As stated above, whether this unit is rented to a person with a disability or someone working with this population, in either case, they will be considered low income by the AMI of Marin County.
- E. <u>Green Building:</u> For new construction or rehabilitation, what will you do to incorporate "green building" principles? A consultant on "green" construction will be consulted and all available materials will be used to accomplish "green" objectives. Lifehouse as the owner is a non-profit agency.
 - o For further information, please call Roy Bateman (473-6698). It's ok to call with any questions at any time.
 - o The current year's application form must be used.
 - Completed applications may be mailed or hand-delivered to the Federal Grants Division, Marin County Community Development Agency, 3501 Civic Center Drive, Room 308, San Rafael, CA 94903-4157.
 - Applications sent by fax or e-mail will not be accepted.
 - This form can be expanded to accommodate additional text, but we encourage you to be brief. You may attach supplementary material. If you need more space for several questions, please answer all questions in sequence. If you'd like to download this form as a Microsoft Word document, visit www.marincdbg.com or www.co.marin.ca.us/depts/CD/main/comdev/FEDERAL/index.cfm.
 - o Don't forget to fill out the Organization Profile form.
 - All County publications are available in alternative formats (Braille, large print, or CD) upon request. Requests for accommodations may be made by calling (415) 473-4381 (Voice), 473-3232 (TDD/TTY), or by e-mail at disabilityaccess@marincounty.org. This form and other County documents are available in alternative formats upon request.

DEADLINE: APPLICATIONS MUST BE RECEIVED BY FRIDAY, DECEMBER 13, 2013, AT 5 P.M.

Remember that we don't accept e-mailed or faxed applications.

K:\Cycle\2014 Cycle\Grant Applications\2014-15 CDBG Application Form.Doc/rov