



JERRICO ASSOCIATES

7454 ✓


SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

CORNER RECORD

Document Number 15-012-18

City of San Rafael County of Marin, California

Brief Legal Description Ptn. Lot 8 Hacienda Sub. 7 RM 85



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey Jan. 24, 2002

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
(A) (B) Found pipe & tag RCE 5948 monument,
± 0.3' deep.

A description of the physical condition of the monument as found and as set or reset:
(C) Set rebar & cap LS 3887
(D) Found old hub and tack, re-set w/ rebar and cap LS 3887.
(E) Set nail in 15" Euke. (6' hi)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on January 24, 2002

Signed [Signature] P.L.S or R.C.E. No. LS 3887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 3, 2002

and examined and filed MAY 7, 2002

Signed [Signature] P.L.S or R.C.E. No. 7128

Title DEPUTY

County Surveyor's Comment _____

