


CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION - DATE OF VISIT October 9 1984



A.P. #15-291-08

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH.


Found standard street monuments on Oakdale Avenue

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 3/4 inch iron pipe, RE 8181, at the easterly corner of Lot 36,
 Oak Woodlands Unit Two (11 Maps 11), San Rafael, California

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



() INDICATES CALC. DISTANCE FOR $\frac{1}{2}$ - $\frac{1}{2}$ TIE
 () INDICATES STANDARD CO. MON. FOUND
 RECORD INFORMATION

SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 No. 8181 Oct 19, 1984
 SIGNED: [Signature]
 L.S. No. 378151
 STATE OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED 10-23 1984
 AND EXAMINED AND FILED 10/24 1984
 BY: [Signature]
 TITLE: PROPERTY OF CALIFORNIA SURVEYOR
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET YES NO

