


CORNER RECORD

Document Number 16-012-17

City of San Rafael

County of Marin, California

Brief Legal Description Lot 54 of 6 RM 62



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8/22/03

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Iron pipes per 23 PM 37
(Note: This survey used orig. monuments of 6 RM 62)

A description of the physical condition of the monument as found and as set or reset:

Set Margarita Drive Corners as shown on "Sketch Map" (over)
1/2" rebars & cap embossed L.S. 5290

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 8/25/03


Signed David Hary L.S. or R.C.E. Number LS 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 27, 2003 and examined and filed SEPTEMBER 9, 2003

Signed _____ Title COUNTY SURVEYOR



County Surveyor's Comment _____

"SKETCH MAP"
Scale: 1" = 100'

