CORNER RECORD)				Number <u>APN 16-031-08</u>
city of <u>San Ra</u>	tael .				Marin , California
Brief Legal Description Mar	garita Drive	e nea	r Sout	herl	y boundary of APN 016-031-08
	CORN			COORDINATES (Optional)	
 	Government Corner Meander		Control Property		N E Zone NAD27 □ NAD83 □ NAD83 Epoch
	Rancho Date of Survey		Other 5		Elev Vert. Datum: NGVD29
Corner – Left as foun	Found and tag	gged 🏻	Establis	hed 🛛	Reestablished Rebuilt
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner. Found Iron pipe with tag labeled RE 3230 on Marganita Drive approximately 0.3' below pavement, monument referrenced with 4 concrete mails (strattlers) and 2 mag nails set on line with Iron pipe and tag. A description of the physical condition of the monument as found and as set or reset:					
This Corner Record was prepared the Land Surveyor's Act on	DAMUAL 30 P.L.S or R TY SURVEYOR'S STA	ny direction	20 25 5 7	506	\(\psi \(\texp\frac{6-30-06}{2} \)
and examined and filed	PLS OFF) <u>6</u> 7.e.E. No.		?	Exp. 12-31-06 No. 7128
County Surveyor's Comment					

