



JERRICO ASSOCIATES
 SUITE 27
 77 MARK DRIVE
 SAN RAFAEL, CA 94903

A.P. # 16-041-07 & 74 6681


CORNER RECORD

1/2

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

- Found pipe L.S. 3775
 - Found nail & R.C.E. 13715 in top step
- Lot 51 Unrecorded map of San Rafael Country Club Heights.




PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Ref. dd. of Hartell 86-54549

Set hub and L.S. 3887

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON May 17 1987
 No. 3887


SIGNED: _____
 L.S. or R.C.E. No.: _____

COUNTY SURVEYOR'S OFFICE
 THE CORNER RECORD WAS RECEIVED May 15 1987
 AND EXAMINED AND FILED BY: Charles E. Murphy
 TITLE: Deputy County Surveyor

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO



JERRICO ASSOCIATES

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

16-041-07 & 74 6681


CORNER RECORD

2/2

COUNTY OF Marin T. _____ R. _____ MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

- Found pipe L.S. 3775
 - Found nail & R.C.E. 13715 in top step
- Lot 51 Unrecorded map of San Rafael Country Club Heights.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Ref. dd. of Hartell 86-54549



Found old hub and R.C.E. 13715 out-of-ground
reset with hub and L.S. 3887

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON May 11 No. 3887 1987

SIGNED: [Signature]
L.S. or R.C.E. No.: 6/30/88

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED May 11 1987
AND EXAMINED AND FILED May 15 1987
BY: [Signature]
TITLE: Deputy County Surveyor

DOCUMENT No. _____
STATEMENT ON BACK OF SHEET YES NO