
| CORNER RECO | | Document Number | 16-113-02 & 03 | |
|---|---|--|--|------|
| City of <u>San Rafae</u> | 1 | County of Marin | , Calif | omia |
| Brief Legal Description | Lots 168 & 169 Map of | Loch Lomond I | Jnit 6, 10 RM 43 MCR | |
| 1 | CORNER TYPE Government Corner Meander Rancho Date of Survey | Control ☐ Property ☑ Other ☐ | COORDINATES (Optional) N E Datum Elev | |
| Corner — Left as | found Found and tagged | Established ☐x | Reestablished Rebuilt | |
| Set monument | of corner found: Evidence used to idents at corners of lots 1 m found original stree on page 2) | 68 & 169 at re | ecord dimensions per | |
| | | | | |
| • | vsical condition of the monument as to x 18" iron pipe with p. | found and as set or res | et: | |
| • | x 18" iron pipe with p | found and as set or res | et: | |
| This Corner Record wa | SURVEYOR'S STATEMENT as prepared by me or under my directions. | found and as set or restantic plug "I ection in conformance $19\frac{94}{}$. | with Signal Figure 1 September | ach |
| This Corner Record wathe Land Surveyors' Act | SURVEYOR'S STATEMENT as prepared by me or under my direction on May 4 L.S. or R.C.E. Nu | found and as set or restant ic plug "I ection in conformance $19\frac{94}{}$. | with SEAL AND SURFESSION NO. 6135 | ach |
| This Corner Record was This Corner Record was | SURVEYOR'S STATEMENT as prepared by me or under my direction May 4 L.S. or R.C.E. Nu COUNTY SURVEYOR'S STATEMEN | found and as set or restant ic plug "I ection in conformance $19\frac{94}{}$. | with SEAL REPORT NO. 6135 | ach |



Page 2 of 2