CORNER RECORD	Document Number <u>A.P.N.</u> 017-191-26
City of SAN RAFAEL	County of MARIN, California
Brief Legal Description LOT 5 , 10 R.M.	
CORNER TYPE  I Government Corner □ Contro	COORDINATES (Optional)  N E NAD27  NAD83
─────────────────────────────────────	ty 🔼 ZoneNAD27 🗆 NAD83 🗆 NAD83 Epoch
Rancho Dother Date of Survey SEP 7. 12,	☐ Elev
Corner – Left as found ⊠ Found and tagged □ Es	tablished ⊠ Reestablished □ Rebuilt □
Identification and type of corner found: Evidence used to identify or pro	ocedure used to establish or reestablish the corner:
	. August
A description of the physical condition of the monument as found and a	as set or reset:
19.20 W. C. 19.20 S.	
TO TO AND A SUPPLY OF THE SECOND	
SURVEYOR'S STATEMENT	DAVID L. DAVID L.
This Corner Record was prepared by me or under my direction in c	onformance with CONTRERAS
the Land Surveyor's Act on NOVEMBER 1, Signed Dwid Unlump.L.S or R.O.E. No. 50	5065 STEP CALIFORNIA
COUNTY SURVEYOR'S STATEMENT	and the same of th
This Corner Record was received	2 OO I SED TACK
·	
and examined and filed	₽ SEAL X Exp. 12/31/02/3
Title DEPUTY	No. 7128
County Surveyor's Comment	CALL
	The second secon
	A STATE OF THE STA

