

JERRICO ASSOCIATES

6894 ✓

CORNER RECORD


SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

Document Number 28-055-01

City of Mill Valley

County of Marin, California

Brief Legal Description Lot 1, Block 2, Tamalpais Land and Water Company
Map No. 5 Rack 1 Pull 2



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey Feb. 29, 2000

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

(A) (B) Found standard monument, per 27 Surveys 36


A description of the physical condition of the monument as found and as set or reset:

(C) (D) Set plug and tag LS 3887 in conc s/w.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Feb. 29 19 2000

Signed [Signature] L.S. or R.C.E. Number 3887




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 10 2000 and examined
and filed MARCH 14, 19 2000.

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____



AVE.