City ofMILL_VALLEY			Document NumberA.P.#_029-022-06 County ofMARIN, California					
	CORNER TYPE		COORDI	NATES (Optior			\$\$P\$\$\text{\$\frac{1}{2}}\$\$	
	Government Corner	_	Control	<u> </u>	E Zone			
	Meander		Property	⊠	Elev Vert. Datur			
	Rancho Date of Survey		Other	<u> </u>	Meas. Units:	Metric □	Imperial 🗖	
Corner- Left as found	Found and tagged	☐ Est	ablished	Reest	ablished 🛚	Rebuilt 🔲		
Identification and type of	corner found: Evidence u	used to iden	tify or pro	cedure used	to establish or	reestablish the cor	ner:	
REESTABLISHED	THE SOUTHWESTERL	Y LINE C	OF LAND	S OF ZAL	KOVSKY -	TOOKER PER 2	9 O.S. 85 USING FOUND	
PIPE AND PLUG	L.S. 5814 AND FOL	JND PIPE	AND PL	_UG L.S. 3	3971 PER	29 O.S. 85.		
A description of the physic	al condition of the monu	ment as fou	ınd and as	s set or reset	: <u>SEE S</u>	SHEET 2.		
	· · · · · · · · · · · · · · · · · · ·							
SUR	VEYOR'S STATEMENT							
This Corner Record was pr	repared by me or under n	ny direction	in conform	mance with			ED LAND SU	
the Level Commence to Act	n FEBRUAR`	Y 16 201	ıs				JUSTO LAND SUPLE	
the Land Surveyor's Act of		1 10, 201	<u></u>			ě	00 PM	
Signed Adurance	2 Legie	P.L.S. or R.G	C.E. No.	P.L.S.	4694		★ No. 4694 T	
							Exp. 9/30/17	
COUNTY	SURVEYOR'S STATEMENT						FIF OF CALL FORM	
This Corner Record was re	ceived	Clay?	Sel i	12 1	2015			
	MARCIL	20	1/0	•		6310	CHARD G. MONITCH	
and examined and filed	MARCH 6) 20	10	· · · · · · · · · · · · · · · · · · ·		— [[\$]\[\int\]	THE STATE OF THE S	
Signed Visit	Din F	P.L.S. or R.C	⊱E. No	7821	····	OF CHIS	MONITCH	
Title County Su	orveyor					11 ~ 1	FCALIFORNIA	
County Surveyor's Comment						1,0	FCALIFO	
							<u> </u>	

