CORNER RECORD		Document Number 029-034-02			
City of _Mill Valley	Co	unty of <u>Marin</u>		, California	
Brief Legal Description Lots 2 & a Portion of 4, 4 R	M 109 (2002	RS 231)	-		
CORNER TYPE Government Corner Control		N T E.	COORDINATES (Option N E		
Meander Rancho	Property () Other	Zone NAD83 Ep	ooch	NAD83	
Date of Survey <u>Octob</u>	er 9, 2007	Vert. Datu Meas. Uni		NAVD88	
Corner- Left as found Found and tagged	Established	Ree	established 🔀	Rebuilt	
Identification and type of corner found: Evidence used Found Iron Pipe & Plug (LS 6649) as shown, per	-				
			·		
	to design the second se		Cot intermediat	e line points	
A description of the physical condition of the monum- Iron Pipe & Plug (RCE 30465) as shown, per 200	ent as found an 12 RS 231.	d as set or reset:	Set intermediate	e ime points,	

SURVEYOR'S STATEME	NT		PROFESSION HALL		
This corner Record was prepared by me or under my direct	tion in conforma	nce with	No. 30465		
the Land Surveyor's Act on Dec 17, 2007			D3/11/2018	3	
Signed P.L.S. or R.C.	E. No. 3046	55	SIVIL OF CALE		
COUNTY SURVEYOR'S STA	TEMENT				
This Corner Record was receivedSEPTEMBER	10,2007		GEO LA	ND SUP	
and examined and filed				Selfer I	
Signed P.L.S. or R.C.	E. No. <u>712</u> 8	?		77 X	
Title COUNTY SURVEYOR			No. 7 No. 7 No. 7	7128	
County Surveyor's Comment			01-0		

Borpels-1297

