CORNER RECORD	Document Number	APN 029-043-59
City of MILL VALLEY		MARIN , California
Brief Legal DescriptionLOT 317 & PTN. 316, 4 RI		
CORNER TYP	COO	RDINATES (Optional)
Government Corner   Co		NAD27   NAD83
─────────────────────────────────────	operty 🕅 Zone	NAD27 NAD83
Rancho 🗆 O	her 🗍 Elev	
Date of Survey	Vert. Datum ———— Meas. Units	n: NGVD29 ☐ NAVD88 ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
Corner - Left as found ☐ Found and tagged ☐	Established 🛛 Reesta	ablished  Rebuilt
Identification and type of corner found: Evidence used to identi	y or procedure used to estal	olish or reestablish the corner:
FOUND 3/4" IRON PIPE MONUMENTS, LS 3971, AS S	HOWN ON 23 OS 55 AND	ON REVERSE
	••	
A description of the physical condition of the monument as four		and the second s
SET REBARS W/CAP, PLS 5296 AND 2x2 HUB & TAG, P	LS 5296 , AS SHOWN ON I	REVERSE
SURVEYOR'S STATEMENT		S H JASSA
This Corner record was prepared by me or under my direction	n in conformance with	
the Land Surveyof's Act of NOVEMBE	R 9, 2010	P. SEAL (S) (LIC.EXP92-31-11)
Signed P.L.S. or R.C.E. No.	PLS 5296	
		THE OF CALIF
COUNTY SURVEYOR'S STATEMEN		
This Corner Record was received <u>JANUARY</u> 20, 20		SO LAND SUN
and examined and filed FEBRUARY 15, 2011		G SEALCA STATE
Signed P.L.S. or R.C.E. No.	. 7128	
Title COUNTY SURVEYOR		No. 7128
County Surveyor's Comment		PROFCALIFOR
	***************************************	

