

CORNER RECORD

Document Number 029-091-04

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LANDS OF CHIN AS IDENTIFIED UPON 1998 MAP 121

CORNER TYPE

Government Corner ☐ Control ☐

Meander ☐ **Property** ☒

Rancho ☐ **Other** ☐

Date of Survey 4/28/14 2011

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 ☐ NAD83 ☐

NAD83 Epoch _____

Elev. _____

Vert. Datum: ☒ NGVD29 ☐ NAVD88 ☐

Meas. Units: ☒ Metric ☐ Imperial

Corner – Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.

REESTABLISH THE NORTHERLY LINE OF LANDS OF CHIN AS IDENTIFIED UPON 1998 MAP 12) & A PORTION OF THE SOUTHWESTERN LINE OF SAME SAID PARCEL. SEE DETAILS ON REVERSE SIDE & ALSO THE CORNER RECORD FOR THIS PARCEL DONE BY THIS OFFICE FILED SEPTEMBER 7, 2010.

A description of the physical condition of the monument as found and as set or reset: SET EITHER
BRASS NAIL & BRASS TAG LS 5379 OR SET 1/2" REBAR WITH
YELLOW PLASTIC CAP AFFIXED TO TOP OF REBAR & DRIVEN
FLUSH WITH SURROUNDING GRADE. YELLOW CAP STAMPED
SCRANTON, PL 5379. SEE LOCATIONS ON REVERSE SIDE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 02 APRIL 20 2011

Signed Charles E. Smith P.L.S or R.C.E. No. RS 5379

COUNTY SURVEYOR'S STATEMENT



This Corner Record was received APRIL 25, 2011

and examined and filed MAY 18, 2011

Signed _____ P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____



UN 1113

