CORNER RECORD	Document Number AP# 029-146-03	
City of Mill Valley	County of Marin , Califo	ornia
Brief Legal Description Lot 10, 7 RM 63		
Government Corner  Meander  Rancho  Date of Survey	Control	
Corner- Left as found Found and tagged	Established Reestablished Rebuilt	]
A description of the physical condition of the monument Property Line points were set as shown hereon, pe	as found and as set or reset: _All Property Corners and	
SURVEYOR'S STATEMENT  This corner Record was prepared by me or under my direction		
the Land Surveyor's Act on October 9, 2013	20465	
Signed P.L.S. or R.C.E. N	No. 30465 HALLBACE HALLBACE	
COUNTY SURVEYOR'S STATE	MENT  No. 30465  No. 30465	
This Corner Record was received OCTOBER 10, 3 and examined and filed OCTOBER 14, 201 Signed P.L.S. or R.C.E. N Title DEPUTY CO. SURVEYOR	2013  3  4  50400  AND TREAT OF CALIFORNIE O	
County Surveyor's Comment	PIROF CALIFORNIA	
	FOFCALIFOR	

