


CORNER RECORD

Document Number APN 029-151-45City of MILL VALLEYCounty of Marin California.Brief Legal Description: LOTS47& 48 AS SHOWN ON 7 RM 63**CORNER TYPE:**

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey _____

COORDINATES

[Optional]

N> _____
E> _____
Zone _____ Datum _____
Elev> _____

CORNER:----- Left as found ☐ Found & Tagged ☐ Established ☒ Reestablished ☒ Rebuilt ☐

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND WELL MONUMENTS AS SHOWN ON 7-RM-63


A description of the physical condition of the monument as found and as set or reset: SET REBAR & CAP,
RCE# 18200, AT LOCATIONS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on JUNE 26 1997 _____

Signed: *Douglas J. Matteson* LS-or RCE # 18200

**COUNTY SURVEYORS STATEMENT**

This corner record was received: JULY 14 1997 _____

and filed JULY 15 1997 _____

Signed: *Robert Darrell Beaumont* Title: Deputy



COUNTY SURVEYOR'S COMMENT _____



Scale 1" = 50.00'

CORNER RECORD MAP
OF LANDS OF
JACOB LEPTICH
BEING LOTS 47 AND 48
AS SHOWN ON
7-RM-63 MARIN CO.
RECORDS

APN 029-151-45

