## **CORNER RECORD**

City of MILL VALLEY County of Marin\_\_\_\_\_California. LOT 30, 10 R.H. 15 Brief Legal Description:\_\_\_\_ DN-93-059412 COORDINATES CORNER TYPE: [Optional] Control N>\_\_ Government Corner E>\_ Property Meander Zone\_ Datum Other Rancho  $\Box$ Elev> Date of Survey CORNER:----Left as found  $\boxtimes$ Found & Tagged Established Reestablished X Rebuilt Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND EXISTING MONUMENTS: SHOWN ON REVERSE A description of the physical condition of the monument as found and as set or reset: SET REBAR & CAP, RCE# 18200, AT LOCATIONS SHOWN ON REVERSE. SURVEYOR'S STATEMENT The corner record was prepared by me or under my direction in conformance with MARCH the Land Surveyors' Act on 2000 LS or RCE #8200 **COUNTY SURVEYORS STATEMENT** This corner record was received: APRIL 3 1999 2000 APRIL 1999 2000 and filed Signed COUNTY SURVEYOR'S COMMENT\_\_\_\_\_

Document Number 029-341-12

