Document Number AP# 030-036-09 **CORNER RECORD** County of Marin California City of Mill Valley Brief Legal Description Portion of Lots 9 & 10, 5 RM 76 **COORDINATES (Optional) CORNER TYPE** Government Corner Control NAD83 NAD27 Zone Meander Property NAD83 Epoch Other Rancho Elev. NGVD29 NAVD88 Vert. Datum: Date of Survey July 22, 2014 Meas, Units: Metric **Imperial** Reestablished X Rebuilt Established Corner-Left as found Found and tagged Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found original Standard Street Mon Per 5 RM 76 & Found Open Iron Pipe per 31 RS 9 A description of the physical condition of the monument as found and as set or reset: Found Open Iron Pipe and found Iron Pipe & Cap (RCE 30465) being the NE Corner of Lands of Deitch-Messina as shown hereon. Set Iron Pipe & Cap (RCE 30465) on the Westerly line, extended Northerly 1.00' as shown hereon. SURVEYOR'S STATEMENT This corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on July 22, 2014 P.L.S. or R.C.E. No. 30465 Signed GIONAL LAND SURPLES COUNTY SURVEYOR'S STATEMENT JULY 24, 2014 This Corner Record was received ___ and examined and filed. P.L.S. or R.C.E. No. <u>782</u> No. 7821 **County Surveyor's Comment**

