


CORNER RECORD

Document Number A.P. # 30-091-5,9#18

City of MILL VALLEY County of MARIN, California

Brief Legal Description APN'S. 30-091-05,09 & 18 OR 505 MILLER AVE.



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- X-CUT IN BASE OF FENCE PER 11 P.M. 64
- FOUND 1" IRON PIPE WITH TAG LS 3226 PER 11 PM 64 & 6 O.S. 101

A description of the physical condition of the monument as found and as set or reset: _____

- FOUND X-CUT AND 1" IRON PIPE APPEARED UNDISTURBED.
- SET LEAD AND TAGS IN CONCRETE IN POSITIONS PER 6 O.S. 101

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MAY 5 19 97.


Signed Robert Walling L.S. or R.C.E. Number PLS 6234



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 19 19 97 and examined and filed MAY 20 19 97.

Signed John M. Wooley Title Deputy



County Surveyor's Comment _____