


CORNER RECORD

Document Number APN: 030-162-01

City of MILL VALLEY

County of Marin State of California.

Brief Legal Description: LOT 306 - Subdivision Map of Sutton Manor Unit 3, 7 R.M. 96



CORNER TYPE:

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES:

[Optional]
N> _____
E> _____
Zone _____ Datum _____
Elev> _____

CORNER: ----- Left as found Found & Tagged Established Reestablished Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS PER OFFICIAL RECORD MAP. - 18 R.S. 53

A description of the physical condition of the monument as found and as set or reset:
Original corners not found: Set points as shown on reverse.



SURVEYOR'S STATEMENT:

The corner record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 2006 2006 _____


Signed: Douglas J Mattoon RCE# 18200

COUNTY SURVEYORS STATEMENT:


This corner record was received: JUNE 13, 2006 _____

and filed JULY 18, 2006 _____

Signed [Signature] Title: COUNTY SURVEYOR




COUNTY SURVEYOR'S COMMENT _____




LEGEND

- ⊙ FOUND 3/4" IRON PIPE NAIL & TAG LS 3971 PER 18 R.S. 53, U.N.O.
- SET REBAR AND PLASTIC CAP R.C.E. 18200, U.N.O.
- U.N.O. UNLESS NOTED OTHERWISE
- SUBJECT PROPERTY LINES
- EXTENSION LINE
- (C) CALCULATED
- (M) MEASURED
- R1 Subdivision Map of Sutton Manor Unit 3 7 R.M. 96



DETAIL A
NOT TO SCALE



1"=30'
PAGE 1 OF 1
APN: 030-162-01

MATTESON ENGINEERING AND SURVEYING
SUITE 210A, 200 GATE FIVE SAUSALITO, CA

SHELL ROAD 40' R/W

