CORNER RECORD	Document Number APN 30-191-07
City ofMill Valley	County of <u>Marin</u> , California
Brief Legal Description Lot 23 Enchanted Knolls	Unit One, 8 RM 27
— — — Meander □ Pr	COORDINATES (Optional) N Departy
Corner – Left as found □ Found and tagged □	Established Reestablished Rebuilt Rebuilt
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found Shelley Drive centerline monuments in front of Lot 19 and Lot 21 of Enchanted Knolls, Unit One, 8 RM 27. Used as Basis of Bearings to reestablish Lot 23 boundary. See reverse side of this Corner Record for detail map: of monuments set and found.	
A description of the physical condition of the monument as found and as set or reset: Found steel pin in standard centerline monument well, of record per 8 RM 27, on Shelley Drive and found 3/4" iron pipe tagged LS 2897 at the southeast corner of Lot 21, 8 RM 27, not of record. Set 1/2" iron pipe with plastic cap stamped LS 3890 at front corners and along sidelines of Lot 23 per 8 RM 27	
SURVEYOR'S STATEMENT	in conformance with
This Corner Record was prepared by me or under my direction	LS 3890
Signed Lacy Of P.L.S or B.C.E. No.	3E90
COUNTY SURVEYOR'S STATEMENT	
This Corner Record was received MARCH 16, 201	SED LAND SUP
Signed P.L.S or R.C.E. No.	7128
Title County Sorreyor	No. 7128
County Surveyor's Comment	
	Name of the second seco
	·

