\$	CORNER RECORD City of MILL VALLEY County of M	030.191.12
	Southly of	nct 1 8 RM 27
	Government Corner Control E Zone Zone	
1	Corner – Left as found ☐ Found and tagged ☐ Established ☐ Re	established 🗷 Rebuilt 🗅
0	Identification and type of comer found: Evidence used to identify or procedure used to esta REEKABUSH THE SIDE & REAR LINES	ablish or reestablish the comer: To LOT 21,
Ato	MAP OF ENCHANTED KNOWS, Unit One	2, 8 RM 27
त्र	OH SHELLEY DRIVE. REFER TO SKET	CHOURGE KECORD
ヺ	SIDE FOR DETAILS.	TO THE THE PROPERTY OF THE PRO
のBKED BY:	A description of the physical condition of the monument as found and as set or reset: WITH PLASTIC CAP EMBOSSED "PLS 5 AT RANDOM POINTS ON THE SIDE E RO DAID Let 21 & Also AT THE NORTHWE FOUND 34" IRCH PIRE, LS 2897 At SOUTH PLAST E	STERLY CORNER
多不	SURVEYOR'S STATEMENT	
24 SC	This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JANUARY 15 2010. Signed DUMON P.L.S or R.C.E. No. PLS 5379	No. 5379 Renewal 6-30-2010
7	COUNTY SURVEYOR'S STATEMENT	OF CAUFOR!
Z X	This Corner Record was received JANUARY 21, 2010	
D) SCRANTOR	signed P.L.S or R.C.E. No. 7128 Title COUNTY. SURVEYOR County Surveyor's Comment	Exp. 12-31-10 * No. 7128
* · · ·		No. 7128
à		

Borpela-1297
JH 11001

Page 1 of 2

