CORNER RECORD	Document N	lumber <u>A.</u>	P.# 033-071-38	<b>Y</b>
City of CITY OF MILL VALLEY	County of	MARIN		, California
Brief Legal Description PARCEL 1 13 0.	S. 53			
CORNER TYPE		OORDINATES (Option	onal)	The second secon
Government Corner	Control □ Property	N. E. Zone NAD83 Epoch		083 🗖
Rancho Date of Survey 12/12	Other	Elev. Vert. Datum: Meas. Units:		VD88 🗖 perial 🗖
Corner- Left as found 🔼 Found and tagged 🗌	Established Rees	tablished Reb	uilt 🗌	
Identification and type of corner found: Evidence FOUND PROPERTY CORNERS (SEE SHEET ,			stablish or reestab	lish the corner:
A description of the physical condition of the mor	nument as found and	as set or reset:	SEE SHEET	2.
OUDVEYOR OF ATTURN				
SURVEYOR'S STATEMEN				
This Corner Record was prepared by me or unde	r my direction in confe	rmance with	/st	O LAND SUP
the Land Surveyor's Act on MARCH 23	2004			DE P. OUTER
Signed Rawrenca P Loyse P.L.S. or	R.C.E. No. P.L.S	4694	\ ★ E	No. 4694 xp. 9/30/05
COUNTY SURVEYOR'S STATE	MENT		Tr.	OF CALI FORM
This Corner Record was received MARCH	24, 2004		,	LAND C
and examined and filed HARCH 25, 2	004			CTACKY
Signed P.L.S. or	<del>R.C.E.</del> No. <u>7128</u>			SEAL Exp. 12(3/06/ ×
1 )			{\\\\ \\ \\	\//
Title <u>COUNTY S</u> URVEYOR				No. 7128
Title <u>COUNTY S</u> URVEYOR  County Surveyor's Comment				No. 7128
				No. 7128

