

JERRICO ASSOCIATES

7305


CORNER RECORD

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

Document Number 33-172-09

City of Mill Valley County of Marin, California.

Brief Legal Description Lot 118 Map of Scott Valley Unit Three 12 RM 78



CORNER TYPE

COORDINATES
(Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey April 29, 1998

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Monument line (A) to (B)


A description of the physical condition of the monument as found and as set or reset:

(C) (D) Found iron pipe and LS 3775

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 29 1998.

Signed [Signature] L.S. or R.C.E. Number LS 3887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 11 1998 and examined and filed MAY 12 1998.

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____

