CORNER RECOR	D	Document Number	A.P. 33-191-06
City of MILL VALL	EY	County of MARIN	, California
Brief Legal Description	LOT 85 PER 12 R.M. 101	- All Park	
	CORNER TYPE COOR  Government Corner Control	E Zone	NAD27
	Meander Propert  Rancho Other  Date of Survey 2/27/14, 4/10	Vert. Datum: Meas. Units:	NGVD29 NAVD88 Metric Imperial
Corner- Left as found	Found and tagged Establishe	d 🔲 Reestablished 🛛 Re	built 🔲
	corner found: Evidence used to identify or p		
PER 12 R.M. 101	AND AS SHOWN ON SHEET 2.		
A december of the university		2F 2F	CT 2
A description of the physic	cal condition of the monument as found and	l as set or reset: SEE SHE	<u> </u>
· · · · · · · · · · · · · · · · · · ·			
	***************************************		
SUR	VEYOR'S STATEMENT		
This Corner Record was pr	repared by me or under my direction in con	formance with	ED LAND SU
the Land Surveyor's Act o	20	. <u>P.L.S. 4694</u>	No. 4694 Exp. 9/30/15
COUNTY	SURVEYOR'S STATEMENT		PRE OF CALIFORNIA
This Corner Record was re	eccived <u>JUNE 17.</u> 7	1014	
and examined and filed	NULY 8,2014		ESJONAL LAND SUB
Signed Ruth	P.L.S. or R.C.E. No.	7821	RICHARD G. SIMONITCH
Title DEPUTY			No. 7821  PART OF CALIFORNIA
County Surveyor's Comment			

