CORNER	RECORU	Agency Index	21-083
		Document Number	
City of MILL VALLE Brief Legal Description	Lot 29, 18 RM 71	County of	MARIN , California
	CORNER T	YPE N	COORDINATES (Optional)
N	LI		Metric U.S. Survey Foot
	A / 27 / 21	Marking Date	Epoch Date
	Date of Survey <u>4/27/21 -</u>	Complies with	Public Resources Code §§8801-8819 Public Resources Code §§8890-8902
PLS Act Ref: X 8765 (d)	□ 8771	□ 8773	Other:
Corner/ Monument: X Left as four Found and	-	Rebuilt Referenced	☐ Pre-Construction ☐ Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description (s):			
This Corner Record was prepa the Professional Land Surveyo Signed	rs' Act on Ma	ection in conformance with y 17, 2021 or R.C.E. No. 6649	L-6649 OF CALFORDITA
This Corner Record was received and examined and filed Signed Title County Surveyor's Comment	07/14/2021 P.L.S.	or R.E.E. No. <u>9797</u>	STATE OF CALIFORNIA

