CORNER RECORD	Document NumberA.P.# 033-220-05
City of MILL VALLEY	County of MARIN , California
Brief Legal Description LOT 5, 18 R.M. 71	
CORNER TYPE CO Government Corner Contr Meander Prope Rancho Other Date of Survey 01/18/12	erty NAD83 Epoch Elev. Vert. Datum: NGVD29 NAVD88 NGVD29 NAVD88
Corner- Left as found 🛛 Found and tagged 🔲 Establish	hed Reestablished Rebuilt
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: REESTABLISHED BOUNDARY OF LOT 5, 18 R.M. 71 BASED ON STREET MONUMENTS FOUND IN UNDERHILL ROAD AS SHOWN ON SHEET 2	
A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.	
CHDVDVODIG CTATEMENT	
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in co the Land Surveyor's Act on JANUARY 18 Signed Signed	2012 LAND SUPLE P. DOLLED OR
COUNTY SURVEYOR'S STATEMENT This Corner Record was received FERUARY 2 and examined and filed MARCH 14, 2012 Signed P.L.S. of R.C.E. N	22, 2012 See TACASO TACAS
Title COUNTY SURVEYOR County Surveyor's Comment	Exp. 12 - 31-12 7

