CORNER TYPE COORDINATES (Optional)  CORNER TYPE COORDINATES (Optional)  Government Corner	CORNER RECORD	APN <u>034-302-07</u>
CORNER TYPE COORDINATES (Optional)    CORNER TYPE COORDINATES (Optional)   N.		
CORNER TYPE COORDINATES (Optional)  Government Corner		
Government Corner   Control   N.	Brief Legal Description Lot 84, Map of The Reedlands U	Jnit 3, 10 RM 4
Government Corner   Control   N.		A comment
Government Corner   Control   N.	CORNER TYPE	COORDINATES
Government Corner   Control   N.   E.   Rancho   Other   Zone   Datum   Date of Survey   March 09, 2005   Elev.      Corner- Left as found   Found and tagged   Established   Reestablished   Rebuilt   Rebuilt		
Meander   Property   E.     Rancho   Other   Zone   Datum     Date of Survey   March 09, 2005   Elev.     Corner- Left as found   Found and tagged   Established   Reestablished   Rebuilt     Identification and type of corner found: Evidence used to identify or procedure to establish or reestablish the corner: Established property corners per found street monuments on Warren's Way as shown on herein sht., 2 and per "Map of The Reedlands Unit 3", recorded in book 10 of Maps Page 4, County of Marin.    A description of the physical condition of the monument as found and as set or reset:	Government Corner □ Control	
Rancho Date of Survey March 09, 2005  Corner- Left as found Found and tagged Established Reestablished Rebuilt   Identification and type of corner found: Evidence used to identify or procedure to establish or reestablish the corner: Established property corners per found street monuments on Warren's Way as shown on herein sht., 2 and per "Map of The Reedlands Unit 3", recorded in book 10 of Maps Page 4, County of Marin.  A description of the physical condition of the monument as found and as set or reset: Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht. 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht. 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received MARCH 17, 2005 and examined and filed APRIL 14, 2005.  Title COUNTY SURVEYOR  To stablished Restablished Resta		y 🗶 E.
Date of Survey March 09, 2005  Elev.  Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt    Identification and type of corner found: Evidence used to identify or procedure to establish or reestablish the corner: Established property corners per found street monuments on Warren's Way as shown on herein sht., 2 and per "Map of The Reedlands Unit 3", recorded in book 10 of Maps Page 4, County of Marin.  A description of the physical condition of the monument as found and as set or reset:  Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht. 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht. 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received MARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  No. 7128	,	
Corner- Left as found   Found and tagged   Established  Reestablished   Rebuilt     Identification and type of corner found: Evidence used to identify or procedure to establish or reestablish the corner: Established property corners per found street monuments on Warren's Way as shown on herein sht, 2 and per "Map of The Reedlands Unit 3", recorded in book 10 of Maps Page 4, County of Marin.  A description of the physical condition of the monument as found and as set or reset: Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht, 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht, 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received MAPCH 17, 2005 and examined and filed APRIL 14, 2005.  Title COUNTY SURVEYOR  To stablished Reestablished Reestablish or re	Date of Survey March 09, 2005	
A description of the physical condition of the monument as found and as set or reset:  Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht. 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht. 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  Title COUNTY SURVEYOR  County Surveyor's Comments		
A description of the physical condition of the monument as found and as set or reset:  Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht. 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht. 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  Title COUNTY SURVEYOR  County Surveyor's Comments		
Established property corners per found street monuments on Warren's Way as shown on herein sht., 2 and per "Map of The Reedlands Unit 3", recorded in book 10 of Maps Page 4, County of Marin.  A description of the physical condition of the monument as found and as set or reset:  Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht. 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht. 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received MARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  Title COUNTY SURVEYOR  County Surveyor's Comments	Corner- Left as found □ Found and tagged □ Est	ablished 📈 Reestablished 🗆 Rebuilt 🗆
Established property corners per found street monuments on Warren's Way as shown on herein sht., 2 and per "Map of The Reedlands Unit 3", recorded in book 10 of Maps Page 4, County of Marin.  A description of the physical condition of the monument as found and as set or reset:  Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht. 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht. 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received MARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  Title COUNTY SURVEYOR  County Surveyor's Comments		-
Surveyor's Statement  Surveyor's Statement  County Surveyor's Statement  County Surveyor's Comments	dentification and type of corner found: Evidence used to identify	or procedure to establish or reestablish the corner:
A description of the physical condition of the monument as found and as set or reset:  Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht. 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht. 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  Title COUNTY SURVEYOR  County Surveyor's Comments		
A description of the physical condition of the monument as found and as set or reset:  Set ½" iron pipe w/ plastic cap, LS 5461 at locations shown on herein sht. 2. Found ½" iron pipe w/ plastic cap, LS 7237, at locations shown on herein sht. 2.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  Title COUNTY SURVEYOR  County Surveyor's Comments		
SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  County Surveyor's Comments	per map of the recentaines office 3, recorded in book 10 of	i waps i age 4, county of warm.
This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  County Surveyor's Comments  County Surveyor's Comments	plastic cap, LS 7237, at locations shown on herein sht. 2.	
This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on March 15, 2005.  Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  County Surveyor's Comments  County Surveyor's Comments		
Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  County Surveyor's Comments Exp. 12-31-06  No. 7128	SURVEYOR'S STATEME	NT
Signed PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  County Surveyor's Comments Exp. 12-31-06  No. 7128	This Corner Record was prepared by me or under my direct	ion in conformance
Signed W LOGAL PLS Number 5461  COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  County Surveyor's Comments  Title COUNTY SURVEYOR  Exp. 9-30-2006 No. 5461  Fig. 9-30-2006 No. 7128		
COUNTY SURVEYOR'S STATEMENT  This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed Title COUNTY SURVEYOR  County Surveyor's Comments  No. 7128	China Malana	( Sym 0.20 2006)
This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed	Signed PLS Num	// +xp. 8-30-2008 /
This Corner Record was received HARCH 17, 2005 and examined and filed APRIL 14, 2005.  Signed		
Signed Title COUNTY SURVEYOR   5   5   Exp. 12-31-06   County Surveyor's Comments No. 7128	COUNTY SURVEYOR'S STAT	EMENT
Signed Title COUNTY SURVEYOR   5   5   Exp. 12-31-06   County Surveyor's Comments No. 7128		DLAHO.
Signed Title COUNTY SURVEYOR   5   5   Exp. 12-31-06   County Surveyor's Comments No. 7128	This Corner Record was received MAPCH 1/5 2005	and examined and
County Surveyor's Comments Exp. 12-31-06 No. 7128		
County Surveyor's Comments	filed <u>APRIL 14,</u> 2005.	# O 1 A
	filed <u>APRIL 14,</u> 2005.	DUNTY SURVEYOR JEGS 🛬
- CECATION	filed APRIL 14, 2005. Signed Title 4	DUNTY SURVEYOR JEGS 🛬
	filed <u>APRIL 14,</u> 2005.	DUNTY SURVEYOR 55 Exp. 12-31-06 No. 7128

