


CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set a 3/4" iron pipe with plastic plug "LS 3775" at the northeast corner of lot 94 "Map of the Reedlands Unit 3" recorded in book 10 of Maps at page 4, Marin County Records.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


As shown

J 1539 Vargas

AP No. 34-305-05

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON February 20 1987
SIGNED: Joseph Britz
L.S. or R.C.E. No.: 3775
EXPIRES: _____
SEAL


REGISTERED PROFESSIONAL ENGINEER
CHARLES E. MURPHY
COUNTY SURVEYOR'S CERTIFICATE
NO. 18632 WAS RECEIVED _____ 19____
AND EXAMINED AND FILED 7-20 1987
Charles E. Murphy
Reg. Co. Surv
STATE OF CALIFORNIA
DOCUMENT NO. _____
STATEMENT ON BACK OF SHEET YES NO

CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set 3/4" iron pipe with plastic plug "LS 3775" at the northwesterly corner of lot 94 "Map of the Reedlands Unit 3" recorded in book 10 of Maps at page 4, Marin County Records.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


As shown

J 1539 Vargas

AP No. 34-305-05


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON February 20 1987

SIGNED: Joseph Gripp
 L.S. or R.C.E. No.: LS 3775
 EXP. DATE: _____



COUNTY SURVEYOR'S CERTIFICATE
 CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 1987
 Exp. 6-30-89 BY Charles E. Murphy
 TITLE: County Surveyor

STATEMENT ON BACK OF SHEET


YES NO

CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set a 3/4" iron pipe with plastic plug "LS 3775" at the most easterly corner of lot 94 "Map of the Reedlands Unit 3" recorded in book 10 of Maps at page 4, Marin County Records.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

As shown
J 1539 Vargas

AP No. 34-305-05


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE SURVEYORS ACT ON February 20 1987

SIGNED: [Signature]
L.S. or R.C.E. No.: No. 3775



COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED 720 1987
NO. 18652 BY [Signature]
TITLE: Surveyor

STATEMENT ON BACK OF SHEET


YES NO

CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set a 3/4" iron pipe with plastic plug "LS 3775" at the southeasterly corner of lot 94 "Map of the Reedlands Unit 3" recorded in book 10 of Maps at page 4, Marin County Records.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


As shown

J 1539 Vargas

AP No. 34-305-05

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)




SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE SURVEYORS ACT ON February 20, 1987
 SIGNED: [Signature]
 L.S. or R.C.E. No. 18652
 EXPIRES OR CALIFORNIA
 SEAL

REGISTERED PROFESSIONAL LAND SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED 5-20 1987
 No. 18652 BY [Signature]
 Exp. 6-30-89 TITLE Rep. Co. Surv.
 DOCUMENT No. _____
 STATE OF CALIFORNIA
 BACK OF SHEET
 YES NO

CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set a 3/4" iron pipe with plastic plug "LS 3775" at the southwesterly corner of lot 94 "Map of the Reedlands Unit 3" recorded in book 10 of Maps at page 4, Marin County Records.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

As shown
 J 1539 Vargas

AP No. 34-305-05

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON February 20 1987
 SIGNED: [Signature]
 I.S. or P.C.E. No. 65375
 EXP. DATE OF CALIFORNIA 12-31-87

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED 2-20 1987
 Exp. 6-30-89
 BY: [Signature]
 CIVIL ENGINEER
 STATE OF CALIFORNIA
 STATEMENT ON BACK OF SHEET YES NO