


CORNER RECORD

Document Number AP# 38-266-14

City of Corte Madera

County of Marin, California

Brief Legal Description Lot 187 of 11 RM 22



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Standard Street Monuments with Brass Pins
Per 11 RM 22

A description of the physical condition of the monument as found and as set or reset: _____

- ① Set Line Stake - 1/2" Rebar & Cap Embossed L.S. 5290
- ② Proj. Prop. Line - Mag Nail & Large Tag L.S. 5290 @ Back Curb

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 22 2003

Signed David Harg L.S. or R.C.E. Number LS 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 24, 2003 and examined and filed AUGUST 4, 2003

Signed _____ Title COUNTY SURVEYOR



County Surveyor's Comment _____

