


CORNER RECORD

Document Number 96-010712

City of Tiburon County of Marin, California

Brief Legal Description Lot 66 (14 RM 22) Reedland Woods Unit 2



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found Standard City Monuments

A description of the physical condition of the monument as found and as set or reset:
Set 3/4" IRON PIPES WITH PLASTIC CAPS, RCE 30465
SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 11-23 1998.


Signed [Signature] L.S. or R.C.E. Number RCE 30465



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 12-2 1998 and examined and filed December 7 1998.

Signed [Signature] Title Deputy



County Surveyor's Comment _____



SCALE: 1" = 40'

PASEO MIRASOL

LOT 67
(14 RM 22)

LOT 75
(14 RM 22)

LOT 66
(14 RM 22)

LOT 76
(14 RM 22)

LEGEND

- FOUND STANDARD CITY MONUMENT
- SET 3/4" IRON PIPE & CAP, RCE 30465

25' 25'

R=740.00' L=154.99' Δ=12°00'00"

R=765.00' L=160.22' Δ=12°00'00"

L = 50.74'
Δ = 03°48'00"

S 78°12'00" W
120.81'

25' 25'

L=95.56' Δ=109°30'00"

S 27°30'00" E

S 12°00'00" E
88.04'

L=143.34' Δ=109°30'00"
R=75.00'

L=61.04' Δ=4°39'49"

R=750.00'

L=159.04' Δ=12°09'00"

R=725.00'

25'
25'

