


CORNER RECORD

Document Number AP# 39-132-05

City of Tiburon

County of Marin, California

Brief Legal Description Lot 54, Map of Del Mar Estates - Unit 2 (10 M 53)



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Street Monuments Per Map of Del Mar Estates - Unit 2 (10 M 53), See Page 2.


A description of the physical condition of the monument as found and as set or reset:

Set 1/2" x 30" iron pipe and plastic cap "PLS 5143" see page 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 6, 2006

Signed [Signature] P.L.S or R.C.E. No. PLS 5143



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 26, 2006

and examined and filed MAY 10, 2006

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____

LEGEND

- FOUND 3/4" IRON PIPE "LS 3226"
- SET 1/2" IRON PIPE AND PLASTIC CAP "PLS 5143"

