

APN 39-222-19


CORNER RECORD

1 of 1

COUNTY OF Marin T. \_\_\_\_\_ R. \_\_\_\_\_ MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT \_\_\_\_\_ 19\_\_



CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

ESTABLISHED MOST N'LY CORNER OF LOT 2 USING RECORD INFORMATION (SEE DRAWING ON BACK)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

5/8" REBAR w/ PLASTIC CAP BRASS TAG REC# 19622 SET AT RECORD LOCATION (WITHIN A PLASTER BOX).

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

SEE DRAWING ON BACK

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON Sept 21, 20

SIGNED: [Signature] No. 19522  
L.S. or R.C.E. No.: \_\_\_\_\_




COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS REVIEWED AND EXAMINED AND FILED 19 20

BY: [Signature] TITLE: \_\_\_\_\_

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET



YES  NO