


CORNER RECORD

Document Number I.N. 1990-26396

City of TIBURON

County of MARIN, California

Brief Legal Description Lot 4, Map of Tiburon Knolls Unit 3, 13-Maps-75, Marin County Records.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

(A) Found hubs remnants; replaced with 3/4" I.D.I.P. with plastic plug "DANSKIN PLS 4794" (B) Found original hub with tag "RCE 12510"; perpetuated with 3/4" I.D.I.P. with plastic plug "DANSKIN PLS 4794" (C) Found hub with tag "LS 3226"; perpetuated with 3/4" I.D.I.P. with plastic plug "DANSKIN PLS 4794" (D) Found original 3/4" I.D.I.P. with nail and tag "RCE 12510" (E) Set hand-hewn 1" diameter redwood line stakes with nail & brass tag "LS 4794"


A description of the physical condition of the monument as found and as set or reset: _____

SEE REVERSE SIDE

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on 8 JUNE 2000

Signed [Signature] L.S. or R.C.E. Number LS 4794



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 20 2000 and examined

and filed JULY 3, 2000

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____