


CORNER RECORD

Document Number A. P. # 039-252-01-02

City of TIBURON

County of MARIN, California

Brief Legal Description LOTS 14 & 15, TIBURON KNOLLS UNIT 2, 19RM9 MCR.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FD. STANDARD STREET MONUMENTS IN RECORD POSITION. RECORD DATA USED TO ESTABLISH CORNER & LINE POINTS AS INDICATED.

A description of the physical condition of the monument as found and as set or reset: GOOD

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on MARCH 19 2000

Signed [Signature] L.S. or R.C.E. Number LS6234




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3-15-2000 1900 and examined

and filed 3-16-2000 1900

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____