


CORNER RECORD

Document Number A.P.N. 39-261-06

City of Tiburon

County of Marin, California

Brief Legal Description Lot 6 Miraflores Project 16 RM 70



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found standard street monuments on the centerline of Miraflores
and a 3/4" I.P. with no tag at the most easterly corner of Lot 6,
A 3/4" I.P. tagged "RCE 11629" at the most northerly corner and a
3/4" I.P. tagged "RCE 12094" at the most westerly corner.

A description of the physical condition of the monument as found and as set or reset: _____


Set 1/2" rebar and plastic cap stamped "RCE 18221" at the most
southerly corner of Lot 6.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on AUGUST 31, 2001

Signed [Signature] PLS or R.C.E. No. 18221



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 9-4-2001

and examined and filed 9-4-2001

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment _____