


# CORNER RECORD

Agency Index 039-261-06 <sup>B</sup> SWAP  
Document Number DPW#19-016

City of TIBURON County of MARIN, California  
Brief Legal Description Lot 6 of Miraflores Project No. 1, 16 Maps 70, MCR

## CORNER TYPE



☐ Government Corner ☐ Control  
☐ Meander ☒ Property  
☐ Rancho ☐ Other

Date of Survey March 18, 2019

## COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_  
Elevation \_\_\_\_\_  
Units ☐ Metric ☐ U.S. Survey Foot  
Horizontal Datum \_\_\_\_\_  
Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
Vertical Datum \_\_\_\_\_  
☐ Complies with Public Resources Code §§8801-8819  
☐ Complies with Public Resources Code §§8890-8902

PLS Act Ref.: ☒ 8765(d) ☐ 8771 ☐ 8773 ☐ Other:  
Corner/Monument: ☐ Left as found ☐ Established ☐ Rebuilt ☐ Pre-Construction  
☐ Found and tagged ☒ Reestablished ☐ Referenced ☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet #2 for description(s):

Found three centerline monuments, two with iron pin, one with L punch per corner record, all three match record information. Found iron pipes at each corner of Lot 6, as shown on Corner Record except southerly corner. Re-establish southerly corner with 5/8-inch rebar & yellow cap, PLS 7950.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on April 25, 2019

Signed [Signature] P.L.S. or R.C.E. No. 7950



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3/20/2019

and examined and filed 5/14/19

Signed [Signature] P.L.S. or R.C.E. No. 9292

Title DEPUTY C.S.

County Surveyor's Comment



