

CORNER RECORD


Document Number A.P. # 39-271-02

City of TIBURON

County of MARIN, California

Brief Legal Description LOT 10 17 R.M. 8

A.P. 39-271-02



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND STREET MONUMENTS ON AVENIOA MIRAFLORES PER
17 R.M. 8

A description of the physical condition of the monument as found and as set or reset: FOUND 1/2" REBAR AND CAP L.S. 5290
RESET LEANING 3/4" PIPE WITH 1/2" REBAR AND CAP L.S. 4694,
SET NAIL AND TAG L.S. 4694 ON CONCRETE WALL, SET 1/2" REBAR & CAP
L.S. 4694 AT ALL OTHER PROPERTY CORNER'S AND ANGLES

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on FEBRUARY 19 97.

Signed Lawrence P. Doyle L.S. or R.C.E. Number P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 2 19 97 and examined and filed APRIL 3 19 97.

Signed John M. Woolley Title Deputy



County Surveyor's Comment _____