

CORNER RECORD


21-146

Agency Index A.P.N. 043-091-06

Document number \_\_\_\_\_

City of MILL VALLEY County of MARIN, California

Brief Legal Description LOT 99 AS SHOWN UPON RECORD MAP  
6 R.M. 69, MARIN COUNTY RECORDS



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey JANUARY, 2021

COORDINATES(Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_  
Elevation \_\_\_\_\_  
Units Metric  U.S. Feet   
Horizontal Datum \_\_\_\_\_  
Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
 Complies with Public Resources Code §§8801-8819  
 Complies with Public Resources Code §§8890-8902

PLS Act Ref.:  8765(d)  8771  8772  Other:

Corner/Monument  Left as found  Established  Rebuilt  Pre-Construction  
 Found & Tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

UTILIZED STANDARD WELL MONUMENT(3/4" IRON PIPE, RCE 3230), AS SHOWN UPON 6 R.M 96 AS A BASIS OF BEARINGS TO MONUMENT THE SOUTHEAST CORNER AND A POINT ON THE WESTERLY LINE OF SAID LOT 99. SAID WELL MONUMENTS MEASURED PER 6 R.M. 96 AND WERE DEEMED UNDISTURBED, AND ARE SHOWN ON THE ATTACHED DIAGRAM.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on July 14, 2021.

Signed \_\_\_\_\_ P.L.S. or R.C.E. No. 7744



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-20-21

and examined and filed 1-31-22

Signed [Signature] P.L.S. or R.C.E. No. 9292  
Title DEPUTY

County Surveyor's Comment

RECEIVED

JUL 20 2021

County of Marin  
Department of Public Works



