


CORNER RECORD

Document Number APN: 043-091-07

City of Mill Valley

County of Marin, California

Brief Legal Description Corner Lots 100/101 Along Carlota Circle, 2 O.S. 153.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 9 December 2005

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NADV88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found 1/2" Iron Pipe And 3/4" Iron Pipe Along Carlota Per 2 O.S. 153. Found 1/2"
Iron Pipe At The Most Westerly Corner Of Lot 256, 6 RM 58. Found 1/2" Iron Pipe On The
Southwesterly Line Of Lot 256, 6 RM 58. Found Old Redwood Hub on Southwesterly Line Of Lot
98.

A description of the physical condition of the monument as found and as set or reset:
Set 3/4" Iron Pipe With RCE 18221 Tag Corner Lots 100/101, 2 O.S. 153.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on DECEMBER 19, 2005.

Signed [Signature] P.L.S. or R.C.E. No.: 18221



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 21, 2005 and examined
 and filed JANUARY 24, 2006.

Signed [Signature] P.L.S. or R.C.E. No.: 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____



