
City of Mill Valley	County of Marin, California
Brief Legal Description Lot 68, 13 RM 18	
	N
Corner- Left as found Found and tagged Esta	ablished 🔀 Reestablished 🔀 Rebuilt 🗌
Identification and type of corner found: Evidence used to iden Found original Standard Street Mons, per 13 RM 18; Fo	ntify or procedure used to establish or reestablish the corner: ound Rebar & Cap, LS 6234 per CR_043-103-05, Apr
A description of the physical condition of the monument as fo Property Line points were set as shown hereon, per 13	ound and as set or reset: All Property Corners and RM 18.
This corner Record was prepared by me or under my direction in cothe Land Surveyor's Act on May 5, 2015 Signed P.L.S. or R.C.E. No.	
COUNTY SURVEYOR'S STATEMEN	NT CF CALIFORNIA
This Corner Record was received 5/8/2015 and examined and filed MAY 11, 2015 Signed P.L.S. or R.C.E. No Title DEPUTY County Surveyor's Comment	7821 RICHARD G. SIMONITCH NO. 7821 TOF CALIFORNIA



	- 1	OF	1
1"	= 50'	DESIGN:	PR
Apr	2015	DRAWN:	PR
2015	-038	CHECKED:	J.L.H
	Apr	1" = 50' Apr 2015 2015-038	1" = 50' DESIGN: Apr 2015 DRAWN:

CIVIL ENGINEERS-LAND SURVEYORS 1539 4th ST., SAN RAFAEL, CA. 94901 (415) 457-6647

Lands of Violich — 171 Great Circle Dr. APN 043-103-11, Mill Valley, Marin County, CA