CORNER RECORD	Document	ent Number043-171-13	
City of MILL VALLEY	County of	MARIN, California	
Brief Legal Description LOT 727 7 R.M.94			
Meander P		N	
Corner- Left as found ☐ Found and tagged ☐ Esta	blished 🛛 Reestal	tablished Rebuilt	
Identification and type of corner found: Evidence used to identi  ESTABLISHED NORTHWEST, NORTHEAST, EAST  BASED UPON FOUND STREET MONUMENTS PE  A description of the physical condition of the monument as four	T, AND SOUTHEAS	AST CORNERS OF LOT 727  ID AS SHOWN ON SHEET 2.	
SURVEYOR'S STATEMENT			
This Corner Record was prepared by me or under my direction the Land Surveyor's Act on MAY 19	in conformance with	SED LAND SUPLIFIED TO SUPLIFIED	ń)
Signed Lawree P.L.S. or R.C.		1. 4694 No. 4694 Exp. 9/30/09	OR ★
COUNTY SURVEYOR'S STATEMENT  This Corner Record was received  JUNE 5, 2	008	OF CALLERENT	
and examined and filed JUNE 26, 200	7.0	2.8	1000
Title COUNTY SURVEYOR		Exp. 12-31- No. 7128	-08/*
County Surveyor's Comment		- Ce CWA	The second secon
	PAGE 1 OF 2	·	

