


CORNER RECORD

Document Number 043-201-09

City of Mill Valley

County of Marin, California

Brief Legal Description Lot 33 13 Rm 18, MCR.



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey \_\_\_\_\_
- Control
- Property
- Other

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Standard Street monuments per the subdivision map 13 Rm 18 (over)

A description of the physical condition of the monument as found and as set or reset:

set 1/2" iron bar with cap embossed LS 5290 (over)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 28, 2012

Signed David Harp L.S. or R.C.E. Number LS 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 29, 2012 and examined

and filed JULY 23, 2012

Signed \_\_\_\_\_ Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

