
CORNER RECORD	Document Number	43-224-05	
City of Mill Valley		Marin	California
Brief Legal Description Lot 419 Map of Strawb	erry, Sub.4	7 RM 10	, cumonna
Brief Legal Description			
CORNER TYPE Government Corner	Control		RDINATES ptional)
Meander Rancho June 10	Property X Other 99□	Zone l	Datum
Corner — Left as found ☐ Found/and tagged ☐	Established [Reestablished X	Rebuilt [
Identification and type of corner found: Evidence used to iden From existing record monuments show			
Southwest, and Southeast corner of	Lot 419, Map	of Strawbern	ry Sub 4,
7 RM 10, Marin County Records. Ref	er to sketch	on reverse s	side.
0			
0			-
O A description of the physical condition of the manument as f			
A description of the physical condition of the monument as t			
O set one half inch rebar with PLS ca	-	- -,	driven-
Set one half inch rebar with PLS ca	ground grade		:
ž		· · · · · · · · · · · · · · · · · · ·	
			September 1997
		and the second s	construction of the control of the statement of
SURVEYOR'S STATEMENT	· .	`\ \	EN LAND SCA
This Corner Record was prepared by me or under my dire	ction in conformanc	re with	S AS J. SCA
H June 16	•	1/4/	SEAL TO SEAL T
the Land Surveyors' Act on	19 <u>99</u> .	1 1	No.5379 2
Signed L.S. or R.C.E. Nu	mber <u>LS 537</u>	9	6-30-00
renewal da	te 6/30/00	12/1	OF CHILD
COUNTY SURVEYOR'S STATEMEN	T		PROFESS/ONL
HThis Corner Record was received JUNE 18	19 <u>99</u> and exa	mined	KIN. WOOD
Sand filed JUNE 21 1999.		NEG.	No. 26450 Exp. 3-31 000
Signed July Mooley Title	DEPUTY		CIVIL
County Surveyor's Comment			C OF CALIFORN
County Surveyor's Comment			
D			
<u> </u>			



Page 2 of 2