
CORNER RECORD	Document Number 43	-402-07
City of MILL VALLEY		
Brief Legal Description NW COR LOT 6 - SET		
CORNER TYPE Government Corner Meander Rancho Date of Survey	Other Zone	COORDINATES (Optional) Datum
Corner — Left as found [Found and tagged [Established Reestablish	ned 🔼 Rebuilt 🗌
Identification and type of corner found: Evidence used to iden RECOVERED STANDARD STREET MO CORNER OF LOT 6 PER BOOK 84 TO REESTABLISH THE LOT 6 AS SHOWN ON SKETT	ONUMENTS AND W C ZO OF RECORD SOUTH WEST COR	ORTHWEST MAPS, PAGE NER OF
A description of the physical condition of the monument as f TAGGED P.L.S. 5296 — 1.4 FET AT NORTHWEST CORNER OF AP# 43-	ET BEHIND BACK	OF SIDEWALL
	<u> </u>	
SURVEYOR'S STATEMENT		SED LAND SURVE
This Corner Record was prepared by me or under my dire the Land Surveyors' Act on NOVEMBER 9. Signed L.S. or R.C.E. Nu	19 <u>94</u> .	5296
COUNTY SURVEYOR'S STATEMEN	Т	ED PROFESSION
This Corner Record was received NOVEMBER 12 and filed 11-14- 1994. Signed Ruchard Oulse Title County Surveyor's Comment	1613 14/1	C23,767 C23,767 C23,767 C171L C17



Page 2 of 2