


CORNER RECORD

APN 47-061-03  
APN 47-012-~~49~~

City of MILL VALLEY

Document Number \_\_\_\_\_  
County of MARIN, California

Brief/Legal Description SEE 26 05 98



CORNER TYPE

COORDINATES  
(Optional)

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 4/17/97

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
SET REFERENCE POINTS ONLY TO FOUND REDWOOD STAKE PREVIOUSLY LOCATED PER 26 05 98 DONE BY THIS OFFICE IN NOVEMBER 1989 / SITE VISIT OF 4/17/97 HUB WAS LOCATED YET IS IN DANGER OF BEING OBLITERATED DUE TO AN EARTH SLIDE.

A description of the physical condition of the monument as found and as set or reset:  
SET 1/2" REBAR PLS 5379 CAP FLUSH WITH GRADE AS REFERENCE POINTS TO PERPETUATE LOCATION OF REDWOOD STAKE SHOWN PER PAGE 2.

DJ SCRANTON SURVEYING  
NOVATO, CALIF

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MAY 8<sup>th</sup> 19 97.  
Signed [Signature] L.S. or R.C.E. Number PLS 5379



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 12 19 97 and examined and filed MAY 14 19 97.  
Signed [Signature] Title Deputy



County Surveyor's Comment \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

