


**CORNER RECORD**

Document Number APN. 047-021-17

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 10, MAP OF DOUGLAS DRIVE GARDENS (10 RM10)



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND STD. STREET MONUMENTS AS PER  
RECORD MAP (10 RM10)

A description of the physical condition of the monument as found and as set or reset:

SET 3/4" IP & PLASTIC PLUG, RCE 30465, SEE PG. 2

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JULY 11 2003

Signed Jay L. H. [Signature] P.L.S. of (R.C.E) No. 30465



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JULY 18, 2003

and examined and filed JULY 25, 2003

Signed [Signature] P.L.S. or R.C.E. No. 30212

Title DEPUTY



County Surveyor's Comment \_\_\_\_\_